

This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

- + *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.
- + Refrain from automated querying Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.
- + *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.
- + *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.


About Google Book Search

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at http://books.google.com/


INDICATOR AND DYNAMOMETER.













. • • • • . •

INDICATOR AND DYNAMOMETER,

WITH THEIR

PRACTICAL APPLICATIONS TO THE STEAM-ENGINE

BY


THOMAS J. MAIN, M.A. F.R.AST.S. PROFESSOR, ROYAL NAVAL COLLEGE, PORTSMOUTE;

AND

THOMAS BROWN, Assoc. Inst. C.E.

FROM THE FOURTH LONDON EDITION. ILLUSTRATED.

PHILADELPHIA:
HENRY CAREY BAIRD & CO.,
INDUSTRIAL PUBLISHERS, BOOKSELLERS AND IMPORTERS,
810 WALNUT STREET.
1883



\6334 THT •M28

6957479

INTRODUCTION.

THE object of the following pages is to extend the knowledge of two instruments connected with the Steamengine, the Indicator and Dynamometer: the tormer of which is of universal application in land and marine engines; and the latter is applicable to those marine engines in which the screw is used as the means of propulsion.

The Indicator is one of Watt's inventions, upon which he was accustomed to place great reliance; and it may not, perhaps, be too much to say, that, in his hands, it contributed mainly to his successive improvements of the Steam-After his patent had expired, and the Engine engine. had become public property, the various makers, it seems, did not at first sufficiently value this useful instrument; for we find Farey, in his work on Steam, complaining that Steam-engines had rather retrograded from neglecting it. However that may be, such is not the case now; for every engine maker is careful to apply it, as the best means of testing the working condition of his engine; yet even now there are many classes of people connected with the Steamengine, such as officers commanding steam-vessels and engineers, to whom a fuller description of the instrument, and the uses to which it may be applied, will be acceptable.

Having felt personally the want of more practical information on the subject in existing works, it has been thought by the Authors that the following pages will supply a deficiency, of which many have complained; and enable those who have not the opportunity of making experiments to gain a more intimate knowledge of the Indicator; and it is hoped that some novel applications of the instrument will at the same time give it a degree of interest among those who are conversant with its ordinary details.

CONTENTS

THE INDICATOR 5
The Indicator scale 8
To graduate the Indicator scale
When the atmospheric line is to be traced 9
The use of the small hole in the side of the stop-cock 9
Method of taking a diagram 9
It is important to have means of shortening or lengthening the string
attached to the Indicator 12
The pressure of the steam and the state of the vacuum on the diagram
do not correspond with the boiler-pressure and condenser-vacuum 13
The part of the engine to which the string should be attached 13
On the general configuration of the diagram under given circumstances. 14
The above curves exhibit what has been going on within the engine 17
The slide diagram
To reduce the motion of the slide when too great
To explain how an alteration in the length of the gab-lever affects the
diagrams
To explain why the accompanying diagram has a different outline from
the standard diagram
Top and bottom diagrams with the slide-rod lengthened
To find the nature of the curve, if the slide-rod be shortened 28
Top and bottom diagrams with the slide-rod shortened 30
The effect on the diagram if the stop on the eccentric be two far ad-
vanced
Top and bottom diagrams with the eccentric stop advanced 31
To ascertain, by inspecting the diagram, if the stop on the shaft be not
sufficiently advanced 32
Top and bottom diagrams with stop of eccentric put back 32
Slide diagrams with eccentric stop wrongly placed
The nature of the diagram when the portways of the cylinder or the
steam-pipe are too small for the size of the cylinder and the speed of
the piston

CONTENTS.

	AGE
Diagram obtained when the steam is throttled	34
On the form of the diagram when the expansive gear alone is used	35
Top and bottom diagrams when working expansively	37
To show the advantage of expansive working over throttling	3 8
The general outline of the diagram may appear satisfactory notwith-	
standing the engine is not in good working order	40
On the series of steps in the upper right-hand corner of the accompany-	
ing diagram	41
To explain why, in certain cases, the steam-line (when the expansive	
gear is used) does not descend so rapidly as in the theoretical curve.	42
To ascertain the horse-power of an engine by means of the Indicator	42
Where accuracy is required, a diagram should be taken from the top and	
bottom of the cylinder	44
A diagram representing the relative motions of the slide and piston at	
every part of the stroke	4 8
To find, separately, the value to be given to the steam and vacuum	,
pressures	49
To estimate the work done in a single stroke of the engine	õõ
Method of employing the Indicator for ascertaining the quantity of	
water evaporated by a boiler	51
To ascertain the friction of the steam engine when working without any	
load,	52
The diagram does not necessarily return into itself and form a closed	
figure	55
To explain why the first diagram is rounded at the upper left-hand	
corner	56
Indicator diagram taken when the engine is worked without condensa-	
tion of the steam	
High pressure diagram	
Diagram obtained when there was no load on the safety-valve	
Air-pump diagram	60
THE DYNAMOMETER	61
Method of obtaining the effective horse-power of an engine by the	
Dynamometer	63
Pressures of steam and the corresponding temperatures and relative vol-	
umes	
Areas of circles of given diameters	65

THE INDICATOR.

THE Indicator appears to fulfil two distinct and very important ends.

- 1. It enables us to discover whether there are any defects in those parts of the machinery by which the steam is admitted to the piston: for instance, it indicates whether the slides are properly set, or leaky; whether the stops on the intermediate shaft are properly placed; whether the steam-ports are large enough; and, consequently, whether a different arrangement of the working part of the machinery would be advisable. In fact, in the hands of a skilful engineer, the Indicator is as the stethoscope of the physician, revealing the secret workings of the inner system, and detecting minute derangements in the parts obscurely situated.
- 2. It discovers, at any instant of time, and under any given circumstances, when it may be desirable to apply it, what is the actual power of the engine.

We will first give a description of the instrument, and then proceed to its various uses.

Plate I. Fig. 1, is an external view of the Indicator, as constructed by Messrs. Maudslay and Field, having half the dimensions of the original in every respect. The dotted lines are intended to show the internal parts. A is a hollow cylinder, whose upper end EH is open; the lower end

being intended to fit into an orifice in some part of the engine (generally the top or bottom of the cylinder) by means of the screw aa; b is a stop-cock, by which, when the instrument is attached, we can, at will, make or cut off a communication with the internal parts of the engine. the hollow cylinder A is a piston mn, packed and fitting steam-tight.* Let us suppose, for perspicuity, the instrument to be in communication with the top of the steamcylinder. Then, when a vacuum is formed above the steam. piston, the atmospheric pressure will force down the piston of the Indicator, and it will remain at its lowest position till fresh steam enters; but it would immediately (unless prevented), on receiving a new impulse, be blown out of the open top HE. To prevent this, and at the same time to enable us to measure the force of the steam, a spiral spring presses with its lower extremity against the surface of the piston, while its upper end rests against the fixed cross-piece c. By this arrangement, the place of the piston will always vary as the pressure of the steam varies; for it is a mechanical fact, that the tension of a spring varies as the extension. Hence the greater the pressure of the steam, the more the spring is compressed; and, on the contrary, as the steam loses its elastic force, the spring expands, and the piston descends. So that, to get a clear idea of the instrument, conceive the piston to be acted on by opposing forces: on the lower surface by the pressure of the steam (continually varying), and on the upper surface by two forces, viz., the pressure of the atmosphere (constant) and the force of the spring (varying so as to balance the steam-pressure).

^{*} In practice this piston must not be packed overtight, for fear of increasing the friction and preventing the free motion of the pencil; but the defect, if.any, must be remedied by keeping melted tallow or oil on the upper anriace.

as the steam-force is perpetually varying, it follows that the piston-tube (de) will be continually rising or falling. pencil (p) be attached to the upper end of this tube (de) in which the spring works, it will describe a vertical straight line on a piece of paper brought into contact with it. This, however, is not sufficient for our purpose. This line would, after it was traced, tell us the maximum and minimum pressure during the stroke: but the pressure at any particular portion of the stroke would still be undetermined. We must, therefore, have some plan similar to that adopted in other cases where the vertical motion of a pencil under particular circumstances is to be registered. In all such instances, the paper on which the variation is to be laid down is drawn horizontally at a certain rate. If, for instance, we were desirous of recording how the pressure varies with the time, the paper must be drawn uniformly, by connecting it with clock-work, or some other apparatus for giving a uniform motion. But this, however, is not usually the desideratum in the steam-engine. Our object is here to have, represented before our eyes, the variation of the pressure for every portion of the stroke of the piston; and this is contrived as follows: the paper is wrapped round a cylindrical barrel C, which is brought back against a stop, by a strong watch-spring contained in the box EF. string passes round the pulley D, and is led away through a fair-leader G, to some part of the engine having a similar motion to the piston cross-head, only much reduced; by which means the watch-spring and the spring are always opposing each other. As the piston rises, the barrel will be pulled from left to right; and, on the contrary, as the piston descends, the string having a tendency to slacken, the barrel will, by the force of the spring, be brought back from right to left. At p is the pencil attached to the upper

end of the tube (dg), and rising and falling with the Indicator-piston; and this can be brought into contact with the paper on the barrel C, or removed from it, at will, by means of the joint at g. The rod az, and another one on the opposite side of the cylinder, serve as guides to the piston.

The Indicator-scale.

The paper is kept on the barrel by means of the strip of metal hi, on which are divisions representing the pres-It will be seen that it is graduated sure of the steam. throughout its whole length, beginning from zero, and proceeding upwards and downwards. Now this zero is the level at which the pencil stands when the instrument is unconnected with the steam-engine, and therefore acted on by the atmospheric pressure above and below the piston. The pencil will be seen at this level in the figure. barrel be made to revolve under these circumstances, a horizontal line will be traced out. This is called the atmospheric, or zero, line. And, therefore, the pencil will also be at this level whenever the steam, taking the place of the atmosphere below the piston, exerts the same pressure: and, consequently, wherever the diagram cuts this horizontal line, the pressure of the steam is 15 lbs. on the inch; when on the level of the marks 1, 2, 3, etc., above this zero, the pressure is 16, 17, 18, etc.; and when on the level of the marks 1, 2, 3, etc., below this, the pressure is 14, 13, 12, etc.

To graduate the Indicator-scale.

Mark the point where the pencil touches the scale when the atmosphere is acting freely on both sides of the Indicator-piston; then, having previously found the area of the

^{*} More strictly, 14.75 lbs, or a quantity differing from this slightly according to the state of the weather.

piston in square inches, multiply the result by 15, and apply it as a weight in lbs. to the under side of the piston. This will cause the pencil to descend through a space corresponding to a decrease in pressure of 15 lbs. Make another mark at the point where the pencil is standing, and divide the intervening space into 15 equal parts, each of which will correspond to 1 lb. pressure. This scale can be continued above the highest division as far as requisite. As an example, let us suppose the diameter of the piston to be $1\frac{5}{8}$ inch, the corresponding area is $5 \cdot 1051$ square inches, and the weight to be attached $15 \times 5 \cdot 1051$, or $76 \cdot 5$ lbs.

When the atmospheric line is to be traced.

The atmospheric line should not be taken till after the rest of the diagram has been completed; because, as the parts become warm by the steam, slight variations occur in its position, depending principally on the alteration in the force of the spring; and since this line serves as the origin from which the pressures are dated, it is necessary to have it laid down as correctly as possible.

The use of the small hole (m) in the side of the stopcock (mb).

It serves to let the air into the cylinder (A) when the steam is cut off by the stop-cock, and thus enables us to take the atmospheric line; the stop-cock performs the office of a three-way cock; for by turning it in one direction we allow the steam to enter, and exclude the external air; and by turning it in the opposite direction we admit the air, and exclude the steam.

Method of taking a diagram.

First, look out for some part of the engine whose mo-

tion is proportioned to that of the steam-piston; taking care that the space moved through at that part shall be somewhat less than the circumference of the traversing barrel;† that is to say, whatever be the diameter of the traversing barrel, let the movement of the part you are looking for be not greater than three times this diameter. Fasten a string firmly to this point, and have a traversing loop in the loose end of the string; it must be of such a length that it may be connected with the string passing round the pulley of the Indicator. Then close the stop-cock of the Indicator, and fix it by the screw (aa) to some orifice previously prepared in the top or bottom of the cylinder.1 Insert the pencil you intend to use in the small hole (p) made for its reception, and clamp it there. The pencil should be hard, and have a fine point, to give as clear and distinct a line as possible. Those used for drawing-instruments, and marked HHH, are probably the best. some pieces of clean writing-paper provided, long enough to be brought round the traversing barrel, and overlap about an inch. Paper previously ruled is useful for this

^{*} That is to say, when you are wishing to find how the pressure varies with the stroke of the engine.

[†] In some engines there is no point except the cross-head of the piston to which the string could be attached. The motion must, in these cases, be reduced by pulleys; the circumference of one pulley being equal to the stroke of the engine, and that of the other to the motion of the Indicator, or they should be to each other in these proportions.

[‡] If the top of the cylinder be chosen, the orifice for the grease-cup will generally answer the purpose. In most cases, however, a pipe leads from the top to the bottom of the steam-cylinder, and the Indicator is attached to this pipe. It is provided with stop-cocks, so that when once fixed, the arrangement is very convenient for taking two diagrams almost simultaneously from the upper and lower part of the cylinder. The only objection to it seems to consist in the tendency of the steam to condense in the pipe. For this reason it is advisable to have the Indicator as close to the cylinder as possible.

purpose, the ruled lines being placed lengthways on the cylinder. Wrap a piece smoothly round the barrel, and fix it by means of the clasp (ih) on which the scale is marked. Then tear away all the surplus paper, and examine what remains, to see if it be quite smooth; for if there be any ridges, the curve will have an irregular appearance, which might lead us to suppose some of the gear for working the slides had become loose, or much worn. Next wind the Indicator-string round the pulley of the barrel D; and connect the hook at its extremity with the loop of the string attached to the engine. Adjust the string by means of the running loop, till you are satisfied of the motion of the barrel; allowing it to make nearly a whole revolution, but examining it most carefully to see whether it becomes slack, or overtaut. The stop-cock (b) may now be opened wide, and the Indicator-piston will immediately start into motion; the piston must be well lubricated, to reduce the friction as much as possible, and at the same time to pre-Let the instrument work for a few seconds, vent leakage. to allow it to become thoroughly heated; and when it has arrived at the same temperature as the steam-cylinder, it is in a fit state to trace its diagram. When satisfied of the working of the machine, take hold of the pencil when it comes to the bottom of its stroke, as it is longer stationary at this part, and bring it gently into contact with the paper. This part of the operation requires some practice; for if the pencil be allowed to come forward too rapidly, the spring at g, by which it is pressed against the barrel, will break the point; and again, if held too long, the force of the steam, suddenly acting on the machine, will force it out of the hand, or break the holder. When left to itself, it will trace out a curve on the paper. As soon as it has made a complete circuit, let the pencil be withdrawn from

the paper (being careful not to take hold of it until at the bottom of its stroke). In order to have the line distinct, the pencil should not go over the same ground twice. off the stop-cock, and the piston will become stationary, both sides being acted on by the pressure of the atmosphere. Bring the pencil again in contact with the paper, and as the barrel traverses, the atmospheric, or zero, line will be drawn. The operation is now complete, as far as the curve is concerned. Withdraw the pencil once more, unhook the line, and take off the traversing barrel. take a fine pointed hard pencil, and before taking the paper from the barrel, mark off upon it the scale of pounds, beginning with the atmospheric line, and proceeding upwards and downwards. After taking the paper from the barrel, it is completed by writing on it the date of the month, the name of the ship, that of the engine (whether starboard or port), top or bottom of cylinder (as the case may be), the number of revolutions, the pressure of steam by steam-gauge, and of condensation by barometer-gauge.

It is important to have means of shortening or lengthening the string attached to the Indicator.

Too much attention cannot be paid to this precaution. If an undue strain be brought upon the string it will stretch, and if the string be too long it will become slack; and in either case the barrel will be stationary for a small interval while the steam-piston is moving, and the curve will not be a true indication of the motion. Indeed, if proper attention be not paid to this point, the diagram may turn out very different from what it ought to be. The corners of the figure will be sharper and better defined, and consequently those little faults of the engine, which it is our object to discover, will be hidden.

The pressure of the steam and the state of the vacuum on the diagram do not correspond with the boiler-pressure and condenser-vacuum.

Both the steam-pressure and the vacuum will be less than that exhibited by the steam and condenser gauges respectively. The difference will depend on the size of the ports, the work the engine has to do, the distance the steam has to travel, the impediments it meets with in its passage from the boiler to the cylinder, and from the cylinder to the condenser.

The part of the engine to which the string should be attached.

It must not be attached to any part indiscriminately. Generally speaking, we wish to obtain the pressure of the steam for different portions of the stroke of the piston; therefore the string must be fastened to some part of the engine having a stroke proportioned to that of the piston, only much reduced. The part selected must be as near the Indicator as other circumstances will permit; for the greater the distance the longer the string, and consequently the greater is the chance of error from its stretching. Caution must be used also to prevent the string from slipping on the rod to which it is attached. One of the best contrivances for giving a free and proper motion to the string is to fix a pulley to the radius-shaft,* to the groove of which the fixed end of the string can be connected. It will be necessary, in other cases, to make use of fair-leaders for the purpose of conveying the motion from the part chosen to the Indicator; and due regard

^{*}A quadrant will suffice, if a complete pulley cannot be fitted to the radius-shaft. In Maudslay's direct engine a pin can be fixed on the main centre of the air-pump beam. In Seaward's direct engine the string may be attached to the centre line of the radius-bar.

must be paid in placing fair-leaders, to ascertain whether the motion of the engine will be fairly represented by the Indicator.

On the general configuration of the diagram under given circumstances.

Let us bear in mind that all vertical ascending motions are caused by an increasing pressure of the steam, and that the descent of the pencil is a consequence of the elasticity becoming diminished. Again, with respect to the horizontal motion, we must first notice, that the pencilmark is traced in a direction opposite to the motion of the cylinder-barrel, because the pencil is fixed in its socket, and the barrel moves beneath it. But as the barrel moves from right to left* (that is, as the pencilmark is traced from left to right on the paper), the steampiston is descending; while, on the contrary, as the pencilmark proceeds from right to left, the piston is coming up.† We shall then arrive at the following general conclusions:

- 1. If the motion of the pencil be vertically upwards, 1 as at 1, the steam-pressure is *increasing*, but the piston of the engine-cylinder is *not* moving.
- 2. If the motion be downwards, as at 2, the steam-pressure is decreasing, but the piston not moving.
- 3. If the line traced be horizontal, thus, $\xrightarrow{8}$ the steam-pressure does not vary, but the piston is descending.

^{*} The reader must imagine himself to be facing the Indicator-barrel, as in Fig. 1. (See Plate.)

[†] This will be the case in one engine, but not necessarily so in another engine; and, moreover, if the string be led in another direction the reverse will happen; but this the practical man can correct for himself according to circumstances, and substitute ascending for descending, and vice versa.

- 4. If the line be thus, $\frac{4}{}$, the steam-pressure does not vary, but the piston is ascending.*
- 5. If the line run as at 5, the steam-pressure is increasing, and the piston is descending.*



6. If the line run as at 6, the pressure is decreasing, and the piston is descending.*



7. If the line run as at 7, the pressure is decreasing, and the piston ascending.*




8. If the line run as at 8, the pressure is increasing, and the piston ascending.*



The following diagram was taken from above the piston of H.M.S. Bee; and what follows will serve as explanation of it, and assist likewise in elucidating what has been before stated.

First, we will put numbers round the diagram, in conformity with the principles laid down in the last para-




graph. Then, supposing the pencil to commence at A, and trace out the curve in the direction of the arrows, we

^{*} See second note on preceding page.

see that the steam preserves its first and highest pressure for a considerable portion of the stroke, viz., from A to C; from C to B the downward stroke continues: but the steam begins to lose its pressure, although at a variable rate, decreasing rapidly at D. At B the motion of the piston ceases; but the steam continues to fall, till at length the pencil moves back nearly horizontally for some space, showing the pressure to continue invariable, although the At F, however, 8 shows the steam-prespiston is rising. sure to increase rapidly and suddenly, the piston still ascending; till, as this oblique line merges into the vertical one at G, we perceive that the piston has arrived at the upper end of its stroke; and the fresh influx of steam drives the pencil up to A. From this point the pencil will retrace the same curve. GD is the atmospheric, or zero line.


This diagram was taken from above the piston, and is usually called the "Top Diagram." Similarly, if we connect the Indicator with the bottom part of the cylinder, we shall get a diagram of the same nature, but all the motions will be reversed, as in the accompanying figure



Top and bottom diagrams exhibited on the same card.

It was stated in the foot-note of p. 10, that the Indicator may be attached to a pipe connected with the top and bot-

tom of the piston, and thus both diagrams may be taken on the same card without shifting the instrument. As this is the plan usually adopted at present, a specimen of the two diagrams is given, which will be as follows:



It will be observed that the two figures face each other, as they evidently ought to do.


The above curves exhibit what has been going on within the engine.

The following drawings, marked I. II. III. IV., are intended to represent the upper steam-port of a steamengine, with a section of the upper portion of the slide, in four different positions. In Fig. I., MN represents the portway, and ST the slide-face. The slide is supposed to be that commonly used in marine-engines, and called the Long D-Slide.*

When the pencil, in tracing out the diagram in p. 15, is at G (or it may be rather before arriving at G), the slide is in the position represented in Fig. 1. and is rising:

^{*} See Marine Steam-Engine (by the authors of this work), Article 125 (Long D-Slide).

so that the steam is about to enter the cylinder. Now this will take place, as the diagram shows, very slightly



before the upward stroke of the piston is accomplished; and since the piston and slide are both on the ascent, the lower edge S will have ascended a trifling space when the piston is at its highest. This slight space, though trifling in amount, is important in its results on the working of the engine. It is denominated the lead of the slide. As the piston descends, the valve continues to rise, and the admitting orifice becomes larger; so that although the piston is gaining speed in its downward course, yet in well-constructed engines the first pressure is continued, as we find in the diagram, through a considerable portion of the stroke.

The slide, however, has already begun its downward motion; and when the pencil arrives at C, it has returned into the position it had in Fig. 1. It is clear that as it continues to descend, no more steam can be admitted; whatever the cylinder contains will remain pent up; and


as the piston continues to move downwards, the steam relaxes its force, and we trace a corresponding depression in the diagram from C to D. But a still greater change is to be expected before the piston arrives at its lowest place. Ere that happens, the slide will have come into the position shown by Fig. III.: for it is found to be disadvantageous to allow the steam to be kept in the cylinder till the end of the stroke; because the entering steam at the reverse stroke would meet with so much opposition, till the vacuum on the opposite side had become tolerably good, that the equability of the motion would be much affected. This being granted, we see that the port will be open for eduction before the end of the stroke; consequently a rapid fall in the curve takes place at D. Moreover, the slide continues to fall, not only after the piston has come to the bottom, but evidently during the greater portion. of the up-stroke: although, after a very short interval, from the great rate at which the steam rushes into a vacuum, the state of the vacuum is nearly unaltered, and but little different from that in the condenser; hence, after turning the right-hand corner, the pencil runs nearly horizontally. At F, however, the slide has returned to the position represented in Fig. III. and is rising; the piston is also rising and near the top; consequently the steam that has not yet made its escape, is pent up; and becoming more and more compressed, the pencil rises rapidly, till, the fresh steam entering, it starts up suddenly to A, and retraces the curve. A similar explanation will account for the bottom diagram.

The slide diagram.

This diagram is one in which the Indicator-string is connected with the cross-head of the slide, and not with that

of the piston; so that the horizontal motion of the pencil backwards and forwards corresponds to ascents and descents of the slide, and vice versa. And this process will give us many particulars of the slide, without the trouble of taking the engine to pieces for measurement. Indicator be in connection with the upper end of the cylinder, it will give us information of the upper slideface; and if with the lower end, of the lower slide-face. As was before stated, the string must be connected with some part having the motion of the slide; but generally it will be necessary to reduce the motion, because the stroke of the slide is more than the Indicator-barrel will allow; in small engines, such as that of the Bee, it may be attached to the cross-head direct. As was remarked. so long as the barrel is moving from left to right, the slide is rising; and when moving from right to left, it is falling; and any rise or fall of the pencilled line is due to the variation in the steam-pressure, as in the common diagram. The difference in the two cases, then, simply amounts to this: that in the common diagram we have changes of pressure corresponding to the motions of the piston-rod. and in the slide diagram we have changes of pressure corresponding to the motions of the slide-rod, the horizontal movement in both cases being similar; so that in reading off either a cylinder or a slide diagram, the laws of motion are precisely the same; and therefore, this once understood, there is no difficulty in reading or comparing both diagrams; and the important thing to notice is, that every sudden change of pressure refers to some prominent epoch in the slide's motion; and consequently we are enabled to trace successively on the paper the various positions of the slide from its lowest point as it cushions the steam, allows fresh ingress, etc., and finally arrives at its highest point.

Below is a slide diagram, obtained by connecting the string to the slide cross-head of the engine of H. M. S. Bee.* The whole length of the figure is the same as the travel of the slide. If not, a method must be adopted to be afterwards explained. When the pencil is at d, the slide is at the lowest point, and the vacuum is very good, as the slide rises till the pencil comes to e; but since we know à priori, that the vacuum remains good in the engine till the cushioning commences, therefore when the slide has risen from d to e, the cushioning commences,



and continues as the slide rises till the pencil arrives at f, when fresh steam enters, and after this epoch the slide still rises till the pencil has reached the point h. As the upper line is not so marked in its character as the lower one, we shall not say any thing of the downward stroke.

^{*} The reader will perceive that in this diagram the steam is of higher pressure than that in p. 15. This is caused by a new boiler having been introduced into the vessel, which is loaded to 10 lbs.

Through the points d, e, f, etc., draw the vertical lines Ad, Be, Cf, Dh, cutting the atmospheric line in A, B, C, D, and the horizontal line EH in E, F, G, H. Suppose EHto be the nozzle of the steam-port, on which the face of the steam-slide moves (the cylinder being for convenience of illustration supposed to be lying horizontally). Then, since when the pencil comes to e the cushioning commences, F must be the upper edge of the port. FF' equal to the depth of the port (which we will suppose known). Again, since when the pencil is at d the slide is at the lowest, therefore we must suppose it to have started from E; and consequently, at starting, the upper edge of the slide was below the lower edge of the port, the space F'E. When the upper edge of the slide arrives at G, fresh steam enters; in other words, the lower edge of the port is at F, and therefore the depth of the slideface is FG. Moreover, since the slide still rises through the space HG, HG will be the greatest amount of opening for steam. The successive positions here spoken of are laid down in the figures under the line EH. FF is the depth of the port. In 1, the slide is at its lowest; in 2, the cushioning is commencing; in 3, the steam is about to enter; in 4, the slide is at its highest.

To reduce the motion of the slide when too great.


When the travel of the slide is greater or less than the breadth of the diagram, let HE be the breadth of the diagram, as in the last paragraph; from H draw HP, making any finite angle with HE, and equal to the travel of the slide. Join PE, and through F and G draw FQ, GR, parallel to EP, and then proceed with the line HP, as in

the last paragraph with the line HE, considering Q to be the upper edge of the steam-port, etc.




To explain how an alteration in the length of the gab-lever affects the diagrams.

If the gab-lever be shortened, the travel of the slide will be increased, but the whole motion will occupy the Now to see the effect of this on the opening same time. and closing of the steam-ports, we will suppose the slide in the middle of its stroke, as in Fig. III. p. 18, and rising to admit steam to the upper port. Then, since the space through which the slide has to move in a given time is increased, it will allow the steam to enter, by assuming the position which it has in Fig. 1. p. 18, earlier than it would have done without the alteration. Also, it follows that the remaining portion of the upward motion will not occupy a longer time, but that the greatest opening for steam will Conversely, as the slide goes down again, it oe increased. will take a longer time before the steam is excluded. Now since the slide is in the middle of its motion about the same time in both cases, the cushioning will commence nearly at the same time; but because fresh steam enters earlier, the lead will be increased; and because the maximum opening is increased, the steam-line will be improved and it will be carried further along, for the admission of steam ceases at a later period; finally, the opening to the condenser taking place about the middle of the slide's stroke, it will be unaffected by the alteration. The same reasoning will show that the vacuum-line is also improved. This explanation is exemplified in the following figure,




which consists of two diagrams, the outer one being that in which the gab-lever had been shortened, and the inner one was obtained by lengthening the gab-lever. A similar alteration will take place in the bottom diagram. The figure in the next page represents three top and three bottom diagrams. The middle one of each represents the normal diagram; the two outside ones those which were taken after the gab-lever had been shortened; and the two inner ones those taken after the gab-lever had been lengthened. It will be seen by this figure, that if any advantage be gained in the top diagram by altering the length of the gab-lever, the same advantage will be gained in the bottom diagram. If therefore it be found that the steam be wire-

drawn at both ports and there be too little lead, both diagrams will be improved by shortening the gab-lever.



To explain why the accompanying diagram has a different outline from the standard diagram in p. 15.

We observe, in the first place, that the steam-line, IK,




is shorter than in p. 15, while the exhaust line, LM, is longer than in the latter; we infer, therefore, that the steam had a shorter time to come into the cylinder, and a longer time to make its escape. We observe, likewise, that the engine had made a considerable portion of its downward stroke before fresh steam was admitted.* Now

^{*} We see in the upper left-hand corner of this diagram the motion marked 5 in p. 15, which does not appear in the normal diagram.

these phenomena can be explained, by supposing from some cause the slide to be removed bodily below the place it had when the former diagram was traced. For let us refer to the series of representations of the slide before Thus the point I shows us the steam comes in later in this diagram than in the former; and the valve is rising; consequently its lower edge will be at some point lower than it would be in ordinary circumstances. Again, the point K of the diagram indicates to us that the steam is cut off again sooner; but the slide is descending; and therefore, also, the lower edge is lower than it ought to be. Again, N being too far from the end of the stroke, we see that the exhaust takes place too early; in other words, the upper edge of the slide is too low. And lastly, the point L (where the cushioning commences) being carried too far to the left, shows us that too great an interval elapses before the upper edge of the slide reaches the upper edge of the port. And, consequently, every part of the reasoning proves to us the fact, that the slide is lower than should have been the case. Now, in pursuing our inquiries, we shall find this is caused by one of two defects, viz.: either the slide-rod is too long, or the eccentric-rod is not of the proper length. But in seeking for the remedy, we must look to the slide rod alone, because its length can be more easily adjusted than the eccentric-rod, by means of the nuts and screw by which it is fastened to the cross-head. The derangement of the engine, when the accompanying diagram was taken, was obtained by lengthening the sliderod three-eighths of an inch. The projection at the point O remains to be noticed, although it would not appear, except in exaggerated cases, such as the one before us. It will be seen that the cushioning takes place from L to O; and consequently the pencil rises, because the steam

is compressed: but the fresh steam does not yet enter; and therefore, as the piston descends, this steam, till now compressed, loses its elastic force, and the pencil drops; till at o a fresh supply enters, and the pencil starts up from o to I, taking a motion compounded of the motion of the piston and the pressure of the steam; for it is to be noticed that the line oI bends sensibly to the right; this arises from the increasing velocity of the piston, and is not observable in the standard diagram, except near the top, because the piston is all but stationary during the short time the steam is entering.

The slide diagram also affords great facilities in discovering disarrangements of those parts of the engine whose office it is to permit the entrance and egress of the steam, because since at those particular times the motion of the piston is so slow, nothing definite can be ascertained. The accompanying diagram was taken while the slide was too low in the casing, on account of the lengthening of the rod.



Now since DC is the amount by which the port is opened for steam, we should expect this to be smaller than in the *standard* slide diagram, p. 22, and on comparing them we find this to be the case. Also the space BA, or the amount of travel of the slide before the communication with the


. At the second of the second

The state of the second

condenser is cut off, is greater than in the standard figure. In all cases BC will be constant.

Top and bottom diagrams with the slide-rod lengthened.

If both diagrams are taken on the same card, the accompanying figure will represent each. The left hand one will give the steam and vacuum lines on the upper side of the piston, and the right-hand one the same on the lower side of the piston; and it will be observed that the former is contracted above and spread out at the lower part, while the opposite effects take place in the other.




To find the nature of the curve, if the slide-rod be shortened.

The opposite effects to those mentioned in p. 26 will take place; that is to say, the upper portion of the diagram will be spread out, and the lower part contracted. The effect is shown in the diagram in next page, to obtain which the slide-rod was shortened three-eighths of an inch.


Note. If the whole slide be of the proper length, it is clear that when we get a faulty diagram, similar to that in p. 25, taken from above the piston, the one taken from beneath it will be similar to the annexed figure, and vice versâ. Hence, therefore, we see one advantage of taking both a top and bottom diagram. But if the one diagram

be similar to one of those just exhibited, and the other be satisfactory, the fault lies with the slide itself, and cannot



be remedied except by the engine-makers; for the slide-faces are not permitted to be cut away or added to without the sanction of those who are responsible for the ship. The only plan the engineer can adopt is, to divide the fault as equally as he can between the upper and lower parts, by lengthening or shortening the rod, according to circumstances. Moreover, we perceive an engineer should not be satisfied that he has done all, when he has obtained a good diagram from one end of the cylinder; because, if the fault lie with the slide, he will be improving one to the injury of the other.

The slide diagram which is given below shows very




clearly that the slide had been raised above the position it had when the diagram in p. 22 was described. For

DC (or the amount of opening for steam) is here increased, and AB is diminished; BC remaining constant as before. Comparing the form of this diagram likewise with that in p. 27, we see they are very dissimilar, especially in that part of the lower curve lying between B and C. The steam-piston evidently comes to the top of its stroke about half-way between B and C, and in the diagram, p. 27, it is observable by the downward course of the curve that fresh steam is not admitted till the piston has descended some small space. But this peculiarity is not to be seen in the above figure, because the cushioning and lead are blended together.

Top and bottom diagrams with the slide-rod shortened.

In this diagram the left-hand figure is spread out on the steam-line and contracted in the vacuum-line, while the opposite effects take place in the other.



The effecton the diagram, if the stop on the eccentric be too far advanced.

All the motions of the slide, whether up or down, take place sooner than ordinary: that is to say, the cushioning, the introduction of fresh steam, the cutting off, and the exhaust, all commence sooner. The curve, therefore, iu-

stead of being like the standard diagram (p. 15), will assume somewhat of a lozenge-shape, the upper left and lower right corners being acute-angled, and the other




two obtuse, as in the above diagram. Again, a little reflection will enable us to discover that *similar* defects will be exhibited in the lower diagram under these circumstances, and not *opposite* defects, as was the case when the slide or eccentric-rod was at fault.

OBS. This curve was obtained by inserting a piece of iron, half an inch thick, between the stop on the eccentric and that on the shaft.

Top and bottom diagrams with the eccentric stop advanced.

Since similar effects take place here under these circum-



stances, the two curves will be similar and facing each

other, and will be represented by the foregoing diagram.

To ascertain, by inspecting the diagram, if the stop on the shaft be not sufficiently advanced.

If the stop be not sufficiently advanced, all the motions of the slide will be later than they would be in a well-constructed engine; consequently, all the upper part of the curve will be drawn towards the right, and all the lower part to the left. And, as in the former case, the same distortion will be observable if a diagram be taken from the lower part of the cylinder. Morever, if the defect be great, we shall meet with the hump in the lower left-hand corner, similar to that before noticed. The following diagram was taken after removing back the stop on the shaft seven-sixteenths of an inch.*




Top and bottom diagrams with stop of eccentric put back.

From what has been previously stated, the reader will


^{*} The stop of one engine may be put back with advantage if the other engine be disabled; for by so doing it will be assisted in turning its centres, from the steam being carried farther over the diagram.

see that the accompanying diagram will correctly represent this case.



Slide diagrams with eccentric stop wrongly placed.

The two following curves represent respectively the slide diagrams taken when the stop was advanced and put back




respectively; and the spaces AB, BC, CD, in each of these are the same as in the standard figure, p. 22, the

only difference being in the form of the curves arising from the altered position of the piston relatively to the slide.

The nature of the diagram when the portways of the cylinder or the steam-pipe are too small for the size of the cylinder and the speed of the piston.

Since the steam will not be able to enter or escape so freely as it ought, the pressure at first entrance will not be maintained for any length of time, and the vacuum will not be formed rapidly enough; the steam and vacuum lines . will therefore lose their horizontality; as is readily perceived in the diagram here given, which was taken from



one of our large engines, afterwards improved by shortening the gab-lever.*

Diagram obtained when the steam is throttled.


The upper line will rapidly decline, for the same reason that it would if the steam-pipe or the port were too small; and it will not be so high altogether as in ordinary cases. The vacuum-line, however, will be better than it would

^{*}The reader will observe that this diagram differs from the preceding top diagrams by being turned end for end; but this depends on the way in which the string is led to the engine, and need not be noticed.

otherwise be; for since the quantity of steam admitted is not so great, the speed of the piston will be reduced. But the exhaust-port is of the same size whether the steam be throttled or not; and therefore there is more time for the expanded steam to rush through this orifice into the condenser; and consequently the vacuum-pressure in the condenser and in the cylinder will be more nearly equal, and better in both, than when the full power is set on.


NOTE. When the pressure declines throughout the stroke of the engine, as it does in the foregoing diagram, on account of the contraction of the admitting orifice, the steam is said to be "wire-drawn."

The accompanying diagram represents three diagrams taken from the *Bee's* engine, the steam being throttled to various degrees.




On the form of the diagram when the expansive gear alone is used.

Let AB represent the whole length of the cylinder; and




when the piston has traversed the space AC, let the ingress of the steam be suddenly stopped. Then, from this epoch, the steam-pressure will decrease, and the pencil begin to descend. Now if the temperature of the steam be unaltered, the pressure will vary inversely as the space it occupies. Divide, therefore, the space CB into intervals CF, FG, etc., each equal to AC; and therefore when the piston is at F, the space AF being twice AC, the pressure of the steam at F is half that at C; at G it will be onethird; at H one-fourth, etc.; and if lines be drawn through C, F, G, etc., parallel to AD, and of the length we have just indicated, making CE = AD, FL = half AD, etc., and through the upper extremities of these lines a free curve LMN, etc., be traced, it will give us an idea of what we ought to expect. But since the slide-valve also acts, we



shall have the modification this would produce too; for the slide-valve is placed between the expansive-valve and the cylinder; it follows, therefore, that the effective volume of the steam intercepted by the expansion-valve is the whole of the space between it and the piston, and the slide-valve interposes an additional barrier when it begins to cut off the steam.* The case, therefore, is somewhat similar to what it would be if there were two expansion-valves, one nearer to the cylinder than the other, and the outer one acting first. This figure exhibits a series of diagrams representing various grades of expansion: here 0 gives the full power of the steam without using the expansion gear; 1, that produced by the first grade of expansion; 2, that produced by the second grade; and so on. It is worthy of remark, that the diagram marked 0, which is that resulting from the slide-valve, closely assimilates to that marked 1, produced by the first grade of expansion, as it should do in well-constructed engines.

Top and bottom diagrams when working expansively.

The two curves will face each other, as in the former cases, and will be represented by the accompanying diagram where the highest grade of expansion is used.



The above expansion-diagrams, taken from above and below the piston when working on a high grade of expansion, serve to show the amount of disturbance in the


^{*} Except in engines fitted with Seaward's slides.

steam-line of the two diagrams which is due to the obliquity of the connecting-rod; and they are of great value in that respect, because they show what error is due to that cause alone; whereas in the diagrams exhibited in pp. 16, 17, and explained in p. 45, the effect is due partly to the connecting-rod and partly to the same cause acting through the eccentric-rod. Now, in the case of expansive working, the action of the eccentric-rod is superseded by a cam, which shuts the expansion-valve at a certain period of the rotation, both in the up and down stroke; or, in other words, the valve will close when the crank makes the same angle with the vertical line, both in the up and down stroke; and since, by inspecting the above diagrams, we see that a greater portion of the stroke has been performed in the one case than in the other, this shows most convincingly the influence which the obliquity of the connecting-rod exerts in disturbing the diagram.

To show the advantage of expansive working over throttling.

The advantage gained will depend on the quantity of steam required to produce a given effect, or on the effect produced by a given quantity of steam. Let us, therefore, consider each of these cases separately; and first, taking the effect to be the same, let us compare the quantities of steam. Now the effect will be the same if the number of revolutions be the same. Let, then, in the first place, a diagram, such as ABCD, be taken when using the expansion cam; and let the number of revolutions be counted, which in this instance was 24. Then, instead of using the expansion gear, let the throttle-valve be partially closed till the number of revolutions be the same as before, viz., 24; then take a diagram such as EFGD. Now we remark that the quantity of steam used during

each stroke may be estimated by the heights of the curves at the points C and G, where the eduction takes place; because these heights exhibit the final pressure, and consequently will give us some idea of the amount. Therefore, because the diagrams show that the engine consumes




a cylinderful of steam of greater pressure when the steam is throttled than when working expansively, it must have consumed a greater quantity; and since the number of revolutions of the engine is the same as before, it follows that the work done is the same. We come, therefore, to the conclusion, that, in order to do the same work, an engine will require less steam when working expansively than when using the throttle-valve.

Next, after the expansion diagram has been taken, let the throttle-valve be partially and gradually closed, till the points C and G (of the former diagram) coincide, as in the following curves.* Then the final pressure of steam, and therefore the quantity expended for each stroke of the

^{*}Some care will be requisite to effect this. The readiest plan is to cut to a point the end of the pencil which does not contain lead, and having inserted it in the instrument, trace out with it a blind curve on the paper, and when we see this curve coincide with the other, we may change ends with the pencil, and trace out the throttle curve.

engine, will be the same: but it was found on making the trial that the number of revolutions with the expansion curve being 24, the number was only 19.6 when the other curve was traced. Now, although it may be argued that the number of revolutions being different the quantity



of steam used in a given time will not be the same, yet as there is such an excess of preponderance in the revolutions when working expansively, we may safely conclude that, if the same amount of steam in a given time had been used, the revolutions, and therefore the work done, by expansion would have exceeded that done by throttling.

The general outline of the diagram may appear satisfactory notwithstanding the engine is not in good working order.

This may happen, because in the hands of an inexperienced person the Indicator may trace an unfaithful representation of the condition of the engine. When the piston is near one end of its stroke, if an undue strain be brought on the string, it will stretch, and the Indicator-barrel remaining stationary while the steam is entering the pencil will have a vertical ascending motion, such as is

represented in the figure. On the other hand, if the barrel come back against its stop before the opposite stroke is




accomplished, the pencil will fall vertically, as in the next figure. These two figures ought to have been precisely



similar, the only cause of difference being the accident of the string.


On the series of steps in the upper right-hand corner of the accompanying diagram.



These arise from the piston of the Indicator being packed over-tight, on which account it descends by a series of jerks, as the steam-pressure relaxes.

To explain why, in certain cases, the steam-line (when the expansion gear is used) does not descend so rapidly as in the theoretical curve traced in p. 35.


This will be the case whenever the expansion-valve is leaky, as it was when the accompanying diagram was taken.



As, for instance, in all cases where the common throttlevalve is used for an expansion-valve.


To ascertain the horse-power of an engine by means of the Indicator.

This is the only accurate way of ascertaining the power of an engine; because, as may be seen, the diagram gives



the pressure on the piston; and hence, knowing the number of revolutions and the length of stroke, the laboring The mean pressure on the piston force can be ascertained. is obtained as follows: Divide the diagram by a series of equidistant vertical lines, as in the figure* (the closer the better, where great accuracy is required), and, taking the horizontal line marked 0 as the origin, draw a series of other lines parallel to it at distances equal to the intervals corresponding to the scale of pounds on the Indicator. This being accomplished, if our object be only to form an estimate of the gross power, observe in the middle of each vertical space the number of pounds included between the steam and vacuum lines to tenths, which will be best done by taking the distance with a pair of compasses, and setting it off on the scale of pounds. Write these in their

^{*} Since it is a difficult geometrical operation to divide a line into a great number of equal parts with any thing like accuracy, the following method may be useful in expediting this part of the work, by means of a scale. The scale consists of a line, such as AN, somewhat longer than the line AB, which is to be divided. Let this scale be divided into the requisite



number of equal parts, as in the figure. Fix one end at A, and turn it round that point till the other extremity N coincides with the line NB, drawn through B at right angles to AB. Then through the several points of division of AN draw lines, parallel to NB, cutting AB in the points a, b, c, d; which will be the points of division required. To those who are frequently in the habit of computing the herse-power of engines from the diagrams, this method will be found very advantageous.

proper columns, as in the figure, along the diagram, and add them together Then divide the gross result by the number of columns, and we obtain the gross average pressure on the one side of the piston during the up and down stroke. From this it is usual to deduct from 1 lb. to 1.5 lbs.. according to the size of the engine, for friction; for small engines have more friction in proportion than larger ones; then the result is taken as the effective pressure per square inch, acting uniformly during one whole revolution. Take now the diameter of the cylinder in inches, and square it; then multiply the product by 7854, the result is the number of square inches in the surface of the piston. Multiply this again by the pressure per square inch, as got from the Indicator, for the whole pressure in pounds on the surface of the piston. And if this be multiplied by the length of a double stroke, and finally by the number of revolutions, we shall obtain the work done by the It is usual to divide this quantity by 33,000 (supposing this to be the number of pounds a horse would be able to raise one foot a minute); and the quotient is then called the horse-power of the engine. If there be two engines, as is usually the case in steamers, this quantity must be doubled. (See note, p. 45.)

Where accuracy is required, a diagram should be taken from the top and bottom of the cylinder.

The diagram taken from the top of the cylinder shows only the pressure and vacuum on the upper side of the piston, and therefore cannot indicate what is going on below the piston. If our object be merely to calculate approximately the horse-power of the engine, and it be in tolerably good working condition, it is not of much consequence whether the diagram be taken from above or be-

low; but if the horse-power is required with any great accuracy, the mean result obtained from the top and bottom diagrams must be used. If the actual state of the engine be required, it is necessary to examine into what is passing both above and below the piston, because the errors in one part may have no connection with the errors in another. This will be the case if the slide is too long or too short; in which case the upper port may be properly covered, and the lower one not so; or the upper slide-face may be steam-tight, and the lower one leaky: but if the Indicator be applied to top and bottom, it will detect all

Then, since diameter of steam-cylinder = 20 inches,

.7854

... Diam. = 400

Area = 314.2000 sq. inches. (See table at end of this work.) But pressure of steam by diagram = 15.05lbs. (with old boiler.) Deduction for friction = 1.50.. Effective pressure per inch = 13.55Square inch in piston = 314.22710 5420 1355 4065 Pressure in lbs. on piston Length of double stroke 17029.64 No. of revolutions 38 13623712 5108892 33:000)647[126:32


The horse-power is now nearly double this amount, because the evaporative power of the boiler has been increased.

19% horse-power.

NOTE. Ex. In the preceding diagram, let the number of revolutions be 38, and therefore the number of single strokes 76.

these inaccuracies, and prevent our attempting to improve the working of one side to the detriment of the other. It ought to be remarked here, that in direct-action engines the diagram from below the piston is generally superior to the other. First, because, since the steam has more work to accomplish, the piston does not run away from the steam so readily, and in consequence the steam-pressure is better maintained; and there is generally a little more lead to the slide, to allow a freer ingress to the steam.

There is also another reason why the one diagram is frequently better than the other. If the reader will inspect the various top and bottom diagrams previously given, he will perceive that the former is always superior to the latter. It is invariably the case with the side-lever




engines, or engines in which the motion is transmitted to the crank in an indirect manner: as, for instance, Maudslay and Field's or Ravenhill and Salkeld's, return-rod engines. with direct-acting engines the opposite to this takes place; for with these the bottom diagram is superior to the top. We will first explain the cause of this difference in the case of direct-acting To make the case simpler, engines. let us suppose the lap to be fitted on the steam side of the slides, so as to cut of the steam when the crank has gone through 90° from the top and bottom centres respectively. Put the piston AB at half-stroke; CD being a section of the cylinder: and let OE,

EF be the corresponding positions of the crank and con-

necting-rod; the crank making necessarily a small acute angle, EOG, below OG: and consequently the steam will not, by our supposition, be cut off till the crank has gone through the angle OEG, or until the piston has risen into some position HK above the middle of the stroke; the distance DK, therefore, will be performed by full steam, and the remaining distance KP by expansive steam. therefore the diagram for the up-stroke will be fairly represented by a figure such as MNIPD. Similarly, in the down-stroke the diagram will be represented by CHRM; and therefore in the case we have supposed, viz., when the steam is cut off after 90° have been performed, the bottom diagram is better than the top. But this supposition was only made to render the explanation more simple; for the same thing will happen if the steam be cut off after any other angle has been performed. The same thing may be represented as follows: Let OB, OB' be the


crank in two positions, making the same angle BOA, B'OC with the vertical. Let also BC B'C' be the connecting-rod in its two corresponding positions of the connecting-rod with centres OCC'; describe the arcs AB, B'C, BE, B'E'. Then it will be found in all cases that the distance CD through which the connecting-rod has descended = AE (the difference of the versines of the arcs AB and BE); but that C'F, the space through which the point C' has been raised, =E'C (the sum of the versines of the arcs B'E' and B'C).



Moreover, it is clear that in side-lever and return-rod engines we must reverse the conclusions to which we have here arrived, because as the crank is descending, the piston is rising instead of falling with the crank.

A diagram representing the relative motions of the slide and piston at every part of the stroke.

If we shut off all ingress of steam to the Indicator by means of the stop-cock m (see Plate), and connect the piston of this instrument with any of the moving parts of the engine, it will give a representation of the motion of that part. Let, therefore, the Indicator-piston be connected, by means of fair-leaders, or otherwise, with the slide; all vertical ascending motions of the pencil will represent the motions of the slide (being upwards or downwards, according to circumstances). Again, let the Indicator-barrel be connected by means of its pulley D with the cross-head of the engine, as in all ordinary cases. will hence follow, that horizontal motions of the pencil will represent the motions of the steam-piston; and consequently, the curve traced out will represent the relative motions of the slide and piston. The figure will be of an elliptical appearance, as in the accompanying tracing,



which is one of these curves on a reduced scale: the pencil being supposed to move in the direction of the arrows. The chief information to be gained from this curve is derived from the means it gives us of ascertaining at what portion of the stroke the steam is cut off. For that purpose, let the engine be brought to rest, when on its upper centre, and make a mark (as at A) where the pencil is stationary; and again, make a mark (as at B) where the pencil remains when the engine is on the bottom centre. Through A and B draw horizontal lines, AC, BD, the whole length of the figure. Then AC representing the down-stroke, Ac will give us that part of the down-stroke performed before the steam is cut off; and, similarly, Bd will represent the same portion of the up-stroke. This is evident, because neglecting the lead of the slide, and supposing it to be correctly set, it begins to open at A and closes at c, opens again at B and closes at d.

To find, separately, the value to be given to the steam and vacuum pressures.

To obtain this, we must get the actual pressure, and not the difference of pressure between the steam and vacuum And therefore we might measure the height of the spaces above the atmospheric line, and the depth of the But, in regard to the steam-line, a difvacuum below it. ficulty has to be surmounted which would not easily be got over by practical men unaccustomed to analytical investigations. It is this: that part of the steam-line is usually above the atmospheric line, and part below it; and the result of the one must be subtracted from the results of the other. This is more particularly to be noticed in cases where the engine is working expansively, and a great portion of the steam line is in consequence below the atmospheric line. The following suggestion will, however, get over the difficulty: and consider the


oisto:

' ani

the of

of onthe iii n-

h [t atmospheric line, as in the following figure, to be 15 lbs. (which is its actual pressure), and reckoning downwards, call the lines below it 14, 13, etc., till we come to 3, 2, 1,



0: the line marked 0 we will assume as that line from which the pressures are measured, and both the steam and vacuum line will be above this new zero line; and the actual pressure of each will, by these means, be ascertained, and not the relative pressure, as compared with that of the atmosphere. In the preceding diagram this second method of computation has been performed; the numbers on the left-hand side beginning from the absolute zero, and the figures along the top and bottom of the curve giving the steam and vacuum pressures respectively. The mean of the steam-pressure is 18.85 lbs., and of the vacuum 3.8 lbs. The difference is 15.05, as we obtained before.

To estimate the work done in a single stroke of the engine.

Let us suppose the piston to be descending; then the steam-pressure acts above the piston, and the vacuum-pressure below the piston; that is to say, the steam-pressure must be got from the top diagram, and the vacuum-pressure from the bottom diagram; and we must, there-

fore, make use of the method proposed in the answer to the last question. Thus, to obtain the mean pressure during the down-stroke, take the steam-pressure from the top diagram, and the vacuum-pressure from the bottom diagram, and subtract the latter from the former. Again, to obtain the pressure during the up-stroke, take the vacuum-pressure obtained from the top diagram, from the steam-pressure got from the bottom diagram. This is the only correct method of arriving at the work done during the down and up strokes respectively.

Method of employing the Indicator for ascertaining the quantity of water evaporated by a boiler.

Fix on any convenient part of the steam-line between that point where the steam is cut off and the opening is made to the condenser; that is to say, between the points C and D of the diagram, p. 15. Observe, by counting the vertical spaces, what proportion the portion of the stroke, as far as this point, bears to the whole length of the stroke. Notice also the pressure of the steam at this point. we shall have a certain fraction of the cylinder filled at each stroke with steam of a given pressure. If now the cubic contents of the cylinder be determined, and the number of times the cylinder is filled per minute, we shall have the quantity of steam of known pressure supplied to the engine per minute. Thus suppose that in the Bee : of the cylinder were filled with steam of 15 lbs, pressure: then, since the number of cubic inches in the cylinder twice filled is 15079.6, the number of revolutions being 34 at the time of experiment, the whole number of inches in a minute = 512526.4, $\frac{9}{10} \times 512526.4 = 461273.76$, and the number of cubic inches of atmospheric steam in an hour = $461273.76 \times 60 = 27676425.60$. But each inch of

water is supposed to form 1711 cubic inches of steam at the atmospheric pressure, and therefore the number of cubic

inches of water evaporated $=\frac{27676425\cdot6}{1711}=16175$; and the

number of gallons of water evaporated $=\frac{16175}{277} = 58$ nearly.


Now, if the theory be correct, this should be the quantity of water evaporated from the boiler, due allowance being made for condensation, etc., in the steam-pipe and passages. But this is far from being the case, for the number of gallons actually evaporated by the boiler was ascertained to be 108 gallons in the hour. The reason for this appears evident. From the violence of the ebullition, the steam is in all likelihood not so dry as that on which careful experiments are made, as is frequently made manifest in the boilers that "prime;" so that, even in good boilers, we may conclude that the steam contains much more watery vapor than it would if it were not so rapidly If so, an inch of water would not under these consumed. circumstances form 1711 cubic inches of steam under the atmospheric pressure, and might perhaps form only onehalf that quantity, which would be requisite to give the proper number of gallons of evaporated water.

To ascertain the friction of a Steam-engine when working without any load.

If we examine the effect of any machine at work, however simple, we shall find a certain amount of power is requisite to overcome the friction of the engine itself. Divest, for example, a common crane of its chain, or any load that may be upon it, and it will still be found that some force must be applied to give motion to the gearing alone; the amount of force depending on the materials used, the mode of fitting, and the quantity of gear set in motion. So it is with the Steam-engine. A certain amount of power is required to overcome the friction of all its parts; and in this respect no two engines will be found alike, so much depending on the goodness of the workmanship, and the nice adjustment of the different parts.

Before proceeding with the method of ascertaining the friction of an engine by the Indicator, we would observe, that the greatest care and judgment are requisite in carrying out this experiment; let no one attempt it unless he see his way clearly; and there are many classes of engines in which the experiment ought not to be tried, such as direct acting paddle-engines; indeed, in all unbalanced engines it would be attended with serious risk, by giving the engine enough steam to work it without its load. But it may be carried out satisfactorily and safely in horizontal engines, because their weights and resistances are The way, however, to proceed is this: the communication-valve must first be closed, because the engine requires an exceedingly small quantity of steam to work it when the paddle-wheels are disengaged. let the blow-valve be opened, to allow any steam that may happen to be in the steam-pipe to escape. The more the vacuum is vitiated before commencing the experiment, the safer it will be; for there is less liability of injury to the engine when first set in motion. With the engines of Bee, it is found necessary to destroy the vacuum, before getting the diagram, by opening the blow-valve, to prevent the engine flying off at too great speed. The throttle-valve must be closed, and the paddles disconnected. After slightly opening the communication and throttle-valves, the slide may be opened gradually and cautiously, to admit the steam to the piston, and the injection must be let on

as carefully as possible. Work the engine a few strokes by hand, and then let it be thrown into gear, and regulate the working by the throttle and communication-valves; the object being to give the engine the same number of revolutions without the paddles as it usually has with them; taking care to have the condenser of the same temperature as in the ordinary working state of the engine.* The Indicator having been previously fixed and adjusted, let a diagram be taken: it will be widely different from that when the load is on. Both the steam-line and vacuum-line will be much below the atmospheric line. The diagram may then be taken off, and divided as in the former case. Let the result of this diagram be worked off in the same manner as the common diagram, and the amount is the work the steam has performed, or in other words, the friction of the unloaded engine. This has been accomplished in the subjoined diagram.



^{*} We would strongly advise the insertion of the bulb of a thermometer in the condenser of every engine, in addition to the barometer-gauge. The bulb must be entirely within the condenser, and the scale (at least that part of it which is above 50° or 60°) outside, in the engine-room. The thermometer chosen for the purpose must be graduated higher than the temperature of the steam in the boiler, otherwise it will burst when the engine is blown through. It must be placed on some part acted on freely by the steam, but free from the splash of the injection-water. When the engine is free from air it will then serve as a most delicate test of the vacuum. The temperature preserved should be about 100°.

This is what is commonly subtracted from the gross result obtained under ordinary circumstances, and denominated friction; but it is manifest that it is much less than the actual friction of the engine when turning the wheels; for the friction of every machine increases with its load; and, moreover, the injection water, etc., raised by the air-pump, increases likewise, and all this goes under the head of friction. The friction of large engines is less in proportion than that of smaller ones. In large engines it is usual to allow 1 lb. on the square inch of the piston for friction, and in small engines from 1.5 to 2 lbs.; and in most cases it would be better, except as a matter of experiment, to trust to this than to attempt the difficulty of ascertaining it.

The diagram does not necessarily return into itself, and form a closed figure.

This only happens because the Indicator-barrel contains the spring which, as has been stated, draws back the barrel directly the string relaxes. But we can by a different arrangement produce a figure of some value, in which the curve proceeds continuously in one direction, and which, therefore, we shall call the "continuous diagram." Let the spring, fitted to the traversing cylinder for bringing it back, be taken out, and also the stop that prevents the cylinder from going too far; because our object is to let the barrel revolve freely. The clasp, by which the paper is usually secured, must also be taken off, and the paper must be secured by turning it over the top of the cylinder, and be folded in such a manner that the pressure of the pencil will help to keep it down. Let now some part of the engine be selected where a double pulley may be fitted to revolve one groove of the pulley having about the same

diameter as the pulley attached to the barrel, and the other to the diameter of the paddle-shaft. A string must be passed round this latter pulley and the shaft, and they will revolve in the same time. Another string must be passed round the pulley of the barrel and the smaller of the two pulleys; and then the Indicator-barrel will revolve nearly in the same time as the engine shaft. And if we suppose the shaft to be revolving uniformly, which it will be nearly, especially where there are two engines, the barrel will have a uniform motion in one direction. If the pencil be put to the paper, as in ordinary cases, when the Indicator-piston is at the lowest, it will commence tracing its curve. It should be allowed to remain for one entire revolution, and longer if convenient, provided one line do not interfere with the other in going twice over the paper.

The chief practical utility of the continuous diagram is, that it serves to show the rate at which the steam-pressure increases or decreases. Looking at the continuous diagram, Plate I. Fig. 2, we observe that the steam-pressure does not arrive at its maximum instantaneously, as many suppose, and as the normal diagram, p. 15, would lead us to believe. The vacuum commences at D and continues to E, the cushioning from E to A; the fresh steam enters at A, and causes the pencil to rise till it reaches its highest at B.

To explain why the first diagram in p. 41 is rounded at the upper left-hand corner.

If we examine this diagram by any of the previous tests, we shall find it presents a difficulty not easily surmounted. For in all former cases we can only correct a defect in this corner at the expense of the lower left-hand and the upper right-hand corners. As the Indicator persisted in giving

this outline, and all attempts according to the foregoing principles (by altering the set of the slides, etc.) failed, it was at length proposed to examine the steam-piston itself; and accordingly, steam was let in at the lower port, and the cock of the grease-cup opened, when it was discovered that the piston was not steam-tight in the cylinder; and therefore, although when the engine was working the first impulse of the steam sufficed to drive the pencil up, yet as soon as the piston had got into motion, the escape of steam by leakage did not allow the pencil to rise so rapidly as it otherwise would have done. This roundness is also observable if the speed of the piston be much increased.

Indicator diagram taken when the engine is worked without condensation of the steam.

It is evident that no part of the diagram can be below the atmospheric line, for the pressure can never be less than that of the atmosphere. And since the steam has not a free escape into the air, but is obliged to force open the foot-valve and delivery-valve, and make its way through the air-pump bucket, the resistance it meets with will cause the pressure to be greater than that of the atmos-



phere. Engines whose steam-pressure is not considerably greater than that of the atmosphere cannot be worked on the high-pressure principle. The foregoing diagram was taken from H.M.S. Bee, whose boiler-pressure at that


time was 7 lbs. In high-pressure engines the diagram will be similar to the above; because the steam, having to escape by the blast-pipe, is pent up, and causes the lower part of the diagram to be above the atmospheric line. In general, the steam and vacuum line must be worked out separately, by the plan proposed in p. 49; for it will be observed, that the lines intersect each other in the diagram. The Indicator for high-pressure engines should be made expressly for the purpose; the scale of pounds should have a higher range, but need not go below the atmospheric line.

This curve presents a singular appearance, from the steam and exhaust line intersecting. Since the cushioning begins at the usual place, that is to say, at the same part of the stroke as when used as a low-pressure engine, the steam pent up on the exhaust side, and commencing with a greater pressure than that of the atmosphere, soon surpasses that of the boiler, so that when the port begins to open, the pressure suddenly falls. Again when the entering steam is cut off, the pressure gradually falls, and before the end of the stroke it is less than that of the eduction; and when open again to exhaust, steam enters from the condenser, and the loop of the right-hand corner is formed.

High-pressure diagram.

The accompanying diagram, taken from a high-pressure engine, exhibits practically what we were led to expect in the foregoing article. The vibrations of the spring of the Indicator cause the curve to be distorted, and probably the lower portion is more sensibly affected from another circumstance which we will explain. In these engines, since each engine discharges into one common blast-pipe, there

will be a reflex action of the waste steam from one engine tending to resist the escape of that from the other. The



effect thus produced is more sensibly manifested when the blast-pipe terminates in a contracted orifice or nozzle.

Diagram obtained when there was no load on the safety-valve.


The safety-valve of the boiler was kept open so as to reduce the steam to the pressure of the atmosphere, and the accompanying series of diagrams was taken at the



various grades of expansion. It differs from that exhibited in the diagram obtained when the injection-water was shut off, in this respect, viz., that the whole of the diagram in the former case was above the atmospheric line, whereas in this all of them are below that line.

Air-pump diagram.

The accompanying diagram is the result of connecting the Indicator with the cylinder-cover of the air-pump of an engine. It was taken by Mr. Eames, chief-engineer,



H.M.S. Inflexible, and was kindly given by him to the authors. To explain it, let us suppose the pencil to be at A when the bucket of the air-pump is at the bottom of its stroke, at which time there will be nearly a vacuum in the air-pump cylinder. As the bucket is raised with the water which it carries, the superincumbent steam becomes compressed, consequently the pencil rises, as in the curve AB. When at some point, B the delivery-valve is forced open, and the pent-up steam makes its escape; after which the pencil drops slightly at C, and exhibits the constant pressure of the water as it goes off by the waste-water pipe. On the descent of the bucket, since the steam has disappeared, the pencil suddenly falls through DE, and continues its course to A horizontally.

THE DYNAMOMETER.

This instrument has been introduced into some screwvessels, for the purpose of enabling the engineer to record the exact amount of pressure given off by the screw-shaft, and, consequently, the force the engine, by means of this instrument, is exerting to propel the ship. It is merely a lever, or a combination of levers; the shaft pressing near the fulcrum, and the farther end of the lever, or combination, being attached to a Salter's spring balance. diagram, Plate I. Fig. 3, AB is the screw-shaft pressing as it revolves against a movable pin which is contained in the plomer-block at C, and can slide freely backwards and forwards; DE is the lever, having the fulcrum at D; the pin at C presses against a knife-edge on the lever, as is seen in the figure. The rod EF is connected with the spring of a Salter's balance, which cannot be seen in the figure, but is concealed from sight by the cylindrical barrel IK; F is also attached to the rod GH. This rod, as we perceive, has several grooves in it, so that the small fork carrying the pencil (p) may be brought in contact with more than one part of the barrel in succession if desirable.

The barrel is made to revolve by means of a strap ab, connecting it with the screw-shaft; and it will be seen by the figure, that there are pulleys of different sizes con-

nected with the bulk-head at M, and the shaft at N, by which the motion of the cylinder can be regulated, and be made quicker or slower at pleasure. The curve will evidently be somewhat similar to the continuous Indicator diagram (Plate I. Fig. 2), consisting of a series of undulations according to the force of the steam and its action on the propeller. A zero-line must be got, as in the case of the Indicator. When the Dynamometer is applied to large engines, the levers can be relieved of the pressure of the shaft; and this being accomplished, the index of the spring-balance will stand at 0, when the zero-line may be traced. The balance will also give the scale of pounds. After the diagram is traced, draw a series of equidistant lines at right angles to the zero-line, as in Plate I. Fig. 4, which represents a Dynamometer diagram taken on board Rattler during her trial with Alecto, the dimensions being reduced one-half. The distance between the curve and zero-line must be measured and compared with the scale of pounds on the balance. Let this be registered on the diagram in its proper space. must be added up, and the sum be divided by the number of spaces taken into account. Thus we shall obtain the mean force of the lever on the spring of the balance; let this be multiplied again by the leverage of the Dynamometer, and the result will be the pressure of the screwshaft on the Dynamometer, and therefore on the vessel.* To obtain the leverage, if the lever be compound, multiply together all the long arms (measuring from the fulcrum),

^{*} A doubt has been expressed by some whether this is really the force exerted by the shaft on the vessel, on account of the shaft acting on a lever that yields to its force; but independently of the fact, that none of the thrust can be lost, it is clear that the thrust at C is equal to the thrust at D and that at E, and these are the two forces acting on the vessel.

and divide the product by all the short arms multiplied together (measuring also from the fulcrum).

Method of obtaining the effective horse-power of an engine by the Dynamometer.

Having found the number of *pounds* pressure exerted by the screw-shaft, multiply it by the speed of the ship in knots, and the product by 6080 (the number of feet in a knot); then divide the result by 60 (the number of minutes in an hour), and by 33,000, and the quotient will be the horse-power.

Or the work may be shortened thus:

Multiply the number of pounds pressure by the speed of the ship in knots, as before, and this product by 00307, and the product gives the horse-power.

This, it will be observed, is the effective horse-power after making allowance for friction and loss by useless resistance.

The diagram before referred to will elucidate the process of working out the result. This was taken simultaneously with two others; and the mean of the three pressures was 41.309 lbs. Multiplying by the power of the system of levers, the result was 8086.4 lbs. (the pressure exerted by the screw-shaft).

The speed of the ship was 9.893 knots.

Hence $8086.4 \times 9.893 = 79998.7$.

And $79998 \times 00307 = 245$ nearly; the horse-power required.

The horse-power by Indicator at the same time was 465.6, showing a loss of 220.6 by friction, resistance, etc.

PRESSURES OF STEAM, AND THE CORRESPONDING TEMPERATURES AND RELATIVE VOLUMES.

Pressure in lbs. per square inch.	Temperature by Fahrenheit.	Relative volume.	Pressure in lbs. per square inch.	Temperature by Fahrenheit.	Relative volume.	Pressure in lbs. per square inch.	Temperature by Fahrenheit.	Relative volume.
1	103-0	20911	25	240.9	1043	49	281.4	564
2	126-0	10890	26	243.2	1006	50	282.7	554
3	141-0	7446	27	245.3	972	51	284.0	543
4	152.2	5690	28	247.4	939	52	285-2	533
5	161-4	4620	29	249.4	910	53	286.4	525
6	169-2	3899	30	251· 4	882	54	287.6	516
7	175-9	3378	31	253.3	856	55	288.8	507
8	182.0	2984	32	255·2	832	56	290-0	499
9	187.4	2675	33	257.1	809	57	291-2	492
10	192.4	2426	34	258-9	787	58	292·4	484
11	197.0	2222	35	26 0-6	766	59	293-6	476
12	201.3	2050	36	262.3	747	60	294 ·8	468
13	205·3	1903	37	264-0	728	61	295 ·9	462
14	209-0	1777	38	265.6	711	62	297-0	455
15	212-9	1669	39	267.2	694	63	29 8·1	448
16	216-3	1573	40	268-8	678	64	299-2	442
17	219-6	1488	41	270-2	663	65	300-2	436
18	222-7	1411	42	271.7	649	66	301.2	430
19	225.6	1343	43	273-2	635	67	302.3	424
20	228.4	1281	44	274-6	622	68	303.3	418
21	231-1	1225	45	276-0	609	69	304.3	413
22	233-8	1173	46	277-4	597	70	305.3	407
23	236.3	1126	47	278-8	585			
24	238-6	1083	48	280-1	574	11	•	1

AREAS OF CIRCLES OF GIVEN DIAMETERS.


DIAM.	AREA.	DIAM.	AREA.	DIAM.	AREA.
20 in.	314.1593	25 in.	490.8739	30 in.	706.8583
j.	318.0985	1	495.7949	1	712.7611
្នំ	322.0623	1	500.7404	1 1	718.6884
3	326.0507	1 3	505.7106	3	724.6403
1	330.0636		510.7052	1 1	730.6167
¥	334.1011	4	515.7244	4	736.6176
3	338.1630	3	520.7681		742.6430
40-44 30-14-0k-14-18	342.2496	선물 - 학생 - 학	525.8364	- (cu (cu - cu)cu - (cu (cu - cu)cu - (cu)cu -	748.6932
21 in.	346.3606	26 in.	530.9292	31 in.	754.7676
}	350.4962	1 1	536.0465	8	760.8668
j j	354.6564]	541.1884		766.9904
3	358.8412	8	546.3549	1 3 1	773.1387
å	363.0503	🖁	551.5459	1	779.3113
5	367.2842	4	556.7615	4	785.5086
ş	371.5424	👸	562.0015	1 4	791.7304
47 -48 - 40 - 40 - 40 - 40 - 40 - 40 - 40	375.8253	न्य अंधान्य विष्युवार्गक	567.2662	14 0300 - 100 v500 034 v 7 00	797.9768
22 in.	380.1327	27 in.	572.5553	32 in.	804.2477
. ₽	384.4646	1	577.8690	<u> </u>	810.5432
j l	388.8212	🗓	583-2072	1	816.8632
3	393.2023	3	588.5701	3	823.2078
<u>.</u>	397.6078		593.9574	1	829.5768
å	402.0379	5	599.3693	1 4 1	835.9705
- <u>\$</u>	406.4926	1 <u>\$</u>	604.8057	👸	842.3886
선가 아무리 전투 사이는 전성도 누구나 없는	410.9719	수 아무 가는 수 나는 한 아무리 나는 아무리 나는 아무리	610.2667		848.8314
23 in.	415.4756	28 in.	615.7522	33 in.	855-2986
1	420.0039	, j	621.2623	3	861.7904
1	424.5568		626.7968	🗓	868-3068
- 2	429.1343	3	632.3561	3	874.8477
j	433.7361	 	637.9397		881.4139
ā	438.3626	š	643.5480	5	888.0030
¥	443.0137	<u>š</u>	649.1807	🛔	894.6176
40-44: 04: 04: 04: 04: 04: 04: 04: 04: 04:	447.6892	수속 가능 수 나는 가는 나는	654.8381	(D-14 10 대한 대한 14 - 대한	901.2567
24 in.	452.3893	29 in.	660-5199	34 in.	907-9203
+	457-1140	1 8	666.2264	1 8	914.6084
1	461.8632		671.9572	1	921.3211
3	466.6370	👼	677.7128	🗿 .	928.0584
i i	471.4352	💃	683.4928	រ៉ូ	934.8202
å	476.2581	4	689.2974	🛔	941.6066
8	481.1055	👸	695.1265	🛔	948.4174
	485.9775	수 가는 아는 아는 아는 아	700-9802	- - - - - - - - - -	955.2529
•		8		s	200 -0-0

968-9973	DIAM.	AREA.	DIAM.	AREA.	DIAM.	AREA.
375-9063 3 1336-4041 3 1753-4506 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7566 3 1360-8129 3 1790-7566 3 1377-2080 3 1790-7566 3 1377-2080 3 1800-1450 3	35 in.	962-1127	41 in.	1320-2543	47 in.	1734-9445
375-9063 3 1336-4041 3 1753-4506 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7304 3 1752-7566 3 1360-8129 3 1790-7566 3 1377-2080 3 1790-7566 3 1377-2080 3 1800-1450 3	}	968-9973	1	1328-3170	1	1744-1852
982-8400 1344-5159 1762-7304 1771-20546 1761-20546 1761-20546 1771-20546 176	. រ្នំ		1		ı	
1 989-7980 1 1352-6520 1 1772-0546 1 1688-9981 1 1781-3936 1 1688-9981 1 1781-3936 1 1688-9981 1 1781-3936 1 1888-9981 1 1888-944 1 1800-1450 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1888-944 1 1 1 1 1 1 1 1 1	l	982-8400	1	1344-5159	1 1	
1781-3936	I		ı		1	
1003·7879	ī		i i		1 1	
1010-8197	ă		l i		1 1	
1024-9568	1		1		7 8	1800.1450
1024-9568	36 in.	1017-8760	42 in.	1385-4424	48 in.	1809-5574
1039-1922	1	1024.9568	1	1393-7013	3	1818-9944
1039-1922	j.	1032-0622]		1 1	1828-4560
1046·3467 1418·6254 1426·9826 1856·9881 1606·7293 1435·3642 1435·3642 1866·5478 1866·5478 1876·1322 1443·7705 1876·1322 1689·7890 1689·7890 1469·1364 1905·33744 1905·3323 1097·1154 1104·4662 1486·1697 1104·4662 1110·44662 1486·1697 1126·6660 1211·92415 1126·6660 1211·9038 1126·6660 1214·7150 1126·6660 1214·7150 1126·1664 1229·1825 1156·3032 1156·3083 1166·1692 1166·1664 1537·8587 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1166·1664 1164·1664 1529·1825 1164·1664 1164·1664 1529·1825 1164·1664 1	3	1039-1922	4	1410-2929	i	1837-9322
1053:5257	į]]	
1060-7293	Ā		1 1			
1067·9575 1443·7705 1876·1322 37 in. 1075·2101 43 in. 1452·2012 49 in. 1885·7410 1082·4873 1460·6565 1895·3744 1089·7890 1469·1364 1905·0322 1104·4662 1486·1697 1924·4218 1111·8416 1494·7234 1934·1534 1119·2415 1126·6660 1503·3012 1126·6660 1503·3012 1126·6660 1503·3012 1144·5885 1511·9038 1511·9038 1953·6902 1144·5885 1529·1825 1156·6083 1156·6083 1164·1564 1150·3036 1164·1564 1171·7282 1164·1564 1171·7282 1166·40346 1166·4034 1171·7282 1166·40346 1166·4034	å		1 4		ı	
1082-4873 1089-7890 1097-1154 1069-7890 1097-1154 1104-4662 1110-4166 1486-1697 1110-4166 1110-4166 1494-7234 1119-2415 1119	1		7		1 1 8	1876-1322
1082-4873 1089-7890 1097-1154 1069-7890 1097-1154 1104-4662 1110-4166 1486-1697 1110-4166 1110-4166 1494-7234 1119-2415 1119	37 in.	1075-2101	43 in.	1452-2012	49 in.	1885-7410
1089-7890	1		1		1	
1097:1154	រុំ		1 1		1 1	
38 in. 1134·1149	3		1 3		1 1	
38 in. 1134·1149	Ĭ		1 1		1 1	
38 in. 1134·1149	Ž.] 🚡		i	
38 in. 1134·1149	ă		8		8	
1141-5885	1 1 8		7 8		7 8	1953-6902
1141·5885	38 in.	1134-1149	44 in.	1520\5308	50 in.	1963-4954
1149·0866	j.		1 1		1	
39 in. 1194·5906	j l		1 1		1 1	
39 in. 1194·5906	ž.		1 1		1 1	
39 in. 1194·5906	Į.		1 1		ľ	
39 in. 1194·5906	Ž		Ž.		Ä	
39 in. 1194·5906	2		8		8	
1202·2605 1599·2777 2052·8467 1209·9550 1608·1518 1217·6740 1617·0390 2072·9727 1225·4175 1625·9705 2083·0723 1233·1856 1233·1856 1240·9782 1248·7954 1643·8874 1248·7954 1652·8827 1248·7954 1652·8827 1248·7954 1661·9025 52 in. 2123·7166 1264·5032 1272·3941 1680·0158 1214·1861	4 7 8		1 1		7 8	2032-8172
1202·2605 1599·2777 2052·8467 1209·9550 1608·1518 1217·6740 1617·0390 2072·9727 1225·4175 1625·9705 2083·0723 1233·1856 1233·1856 1240·9782 1248·7954 1643·8874 1248·7954 1652·8827 1248·7954 1652·8827 1248·7954 1661·9025 52 in. 2123·7166 1264·5032 1272·3941 1680·0158 1214·1861	39 in.	1194-5906	45 in.	1590-4313	51 in.	2042-8206
1209-9550	,		, -			2052.8467
40 in. 1256·6370 46 in. 1661·9025 52 in. 2123·7166 1264·5032	ĵ.		1 1			2062.8974
40 in. 1256·6370 46 in. 1661·9025 52 in. 2123·7166 1264·5032	\$		1 3			2072.9727
40 in. 1256·6370 46 in. 1661·9025 52 in. 2123·7166 1264·5032	រុំ				i i	
40 in. 1256·6370 46 in. 1661·9025 52 in. 2123·7166 1264·5032	i		1		ı Z	
40 in. 1256·6370 46 in. 1661·9025 52 in. 2123·7166 1264·5032	å		3		8	
1264·5032	Ž		3 8		17 8	2113.5188
1264·5032	40 in.	1256-6370	46 in.	1661-9025	52 in-	2123-7166
1 1272-3941 1 1680-0158 2144-1861	1				1 1	
1280·3094	į		🗓		1 1	
1288-2493	\$		3		1 1	
1296·2138	\$		8		8	
1304-2027 1716-5368 2185-4195	2 4		2		2 A	
1 101 010	å		8		8	
	1	1312-2163	1	1725.7284	1 1	2195.7893

DIAM.	AREA.	DIAM.	AREA.	DIAM.	AREA.
ə3 in	2206.1834	59 in.	2733-9710	65 in.	3318:3072
	2216.6022		2745.5681	1	3331.0822
40 -44 1/10 -64 tipo sije rijo	2227.0456	선물 기술 기업 수 있는 경우 기업	2757.1893	i	3343.8818
1	2237.5132	1	2768-8355	1 1	3356.7059
8	2248.0059	F	2780.5059	8	3369.5545
9	2258-5229	7	2792.2010	T T	3382.4277
8	2269.0644	1 8	2803.9205	8	3395.3253
7	2279.6305	4	2815.6647	ajos-tajo cajos esperado	3408·2476
8	2219 0305	8	2019-0041	8	3400 2410
54 in.	2290.2110	60 in.	2827-4334	66 in.	3421-1944
j j	2300.8362	1 1	2839.2266	1 1	3434.1657
1	2311.4759	1	2851.0444	1 1	344 7·1616
ă.	2322.1392	1 4	· 2862·8868	š	3460.1820
Ĭ	2332.8289	1	2874.7536	i	3473.2270
ā	2343.5423	- 5	2886.6450	1	3486.3966
š	2354-2801	å	2898.5610	å	3499.3906
do -4e z o-jo cipo cipo ciper-jo	2365.0426	10 -44 200 -40 v20 v24 v10	2910-5016	col-seles caps tode-color	3512.5093
55 in.	2375-8294	61 in.	2922-4666	67 in.	3525.6524
	2386.6411		2934·4562	,	3538.8201
\$ 1	2397.4770	-to-+4-300pa-5to sq4-7-to	2946.4703	🛊	3552.0123
7	2408:3377	4		1 1	
₹		9	2958-5091	1 1	3565-2292
ģ	2419-2227	2	2970.5722	2	3578-4704
sio-lo-cic cic vol-rois	2430.1775	#	2982.6600	e de cape volte capa	3591.7363
Ž	2441.0666	1	2994.7723	1 1	3605.0267
ŧ	2452.0254	\$	3006.9092	8	3618-3417
56 in.	2463.0086	62 in.	3019-0705	68 in.	3631-6811
ģ	2474.0145	1	3031.2560	1 1	3645.0451
1	2485.0489	1 1	3043:4670	4	3658.4337
¥	2496.1059	i i	3055.7021	i i	3671.8469
រុំ	2507-1873	i i	3067-9616	1	3685.2845
å	2518-2934	Ā	3080-2458	4	3698.7468
ន្ទ័	2529.4239	, š	3092.5544	3 /	3712.2335
oj-seps ade voj- ade:	2540.5781	40 -44 Alo -40 cio estercio	3104.8877	April order Color	3725.7450
57 in.	2551.7586	63 in.	3117-2453	co :	9790-0007
	2562.9629		3129.6273	69 in.	3739·2807 3752·8411
持		8		8	
4	2574.1916	4438-121-50 5478	3142.0344	1	3766.4260
ŧ	2585.4450	\$	3154.4659	§	3780.0356
\$.	2596.7227	2	3166-9217	1 1	3793.6695
₽	2608-0251	l ĝ	3179-4022	8	3807.3281
o de composições de c	2619.3520	1 1	3191.9072	SIDO - NO SIDO SIDO SIDO SI	3 821·0112
1	2630.7035	7	3204·4368	1 1	3834.7189
58 in.	2642.0794	64 in.	3216-9909	70 in.	3848-4510
)	2653.4800	1	3229.5695	흉	3862-2077
j.	2664.9051	ļ	3242.1707	j j	3875.9890
3	2676.3549	1 3	3254.8005	1 3	3889.7948
į	2687.8289	1 1	3267.4527	l I	3903.6252
Å	2699.3277	å å	3280.1296	4	3917.4802
\$ \$	2710.8508	\$	3292.8309	8	3931.3596
tu opo sper je	2722.3988	do 14 you do sto ga 14	3305.5566	-†erzios-busto ejer-je	3945.2636
8		8	3000 0000	8	3340 2000

71 in. 3959·1921 77 in. 4656·6257 83 in. 5410 3973·1452	0:6079 3:9172 3:2511 0:6096 5:9923 2:3998 3:8318
1	3·9172 3·2511 9·6096 5·9923 2·3998 3·8318
\$\frac{39}{4} \frac{39}{14} \frac{39}{29} \frac{1}{4} \frac{468}{4} \frac{9126}{4702 \cdot 0929} \frac{1}{4} \frac{544}{545} \frac{1}{4} \frac{1}{545} \frac{1}{4} \frac{1}{545} \frac{1}{4} \frac{1}{545} \frac{1}{4} \frac{1}{545} \frac{1}{	3·2511 9·6096 5·9923 2·3998 3·8318
\$\frac{1}{8} \frac{4001\cdot 1252}{4015\cdot 1518} \frac{1}{8} \frac{4702\cdot 0929}{4717\cdot 2977} \frac{1}{8} \frac{5457}{5457} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8} \frac{1}{8}	9·6096 5·9923 2·3998 3·8318
	5·9923 2·3998 3·8318
1 + 4015:1518 + 4717:2977 + 5473	2·3998 3·8318
1000 0007	3.8318
4029.2031 4 4732.5271 4 549	
$\frac{2}{8}$ 4057.3884 $\frac{2}{8}$ 4763.0595 $\frac{2}{8}$ 5528	5.2884
72 in. 4071·5041 78 in. 4778·3624 84 in. 554	·769 4
\frac{1}{8} 4085.6532 \frac{1}{8} 4793.6890 \frac{1}{8} 5556	3· 2 751
\$\frac{4080^{6032}}{4099^{8275}}	Ŀ 8053
\$\frac{1}{4}\$ \$4099.8275 \$\frac{1}{4}\$ \$4809.0420 \$\frac{1}{4}\$ \$557.\$ \$\frac{1}{4}\$ \$414.0260 \$\frac{1}{3}\$ \$4824.4187 \$\frac{1}{3}\$ \$559\$ \$\frac{1}{4}\$ \$4128.2490 \$\frac{1}{4}\$ \$4855.2455 \$\frac{1}{3}\$ \$4142.4967 \$\frac{1}{3}\$ \$4855.2455 \$\frac{1}{3}\$ \$562.\$ \$\frac{1}{4}\$ \$470.7958 \$\frac{1}{4}\$ \$470.7958 \$\frac{1}{4}\$ \$4171.0656 \$\frac{1}{4}\$ \$486.1707 \$\frac{1}{4}\$ \$565\$ \$\frac{1}{4}\$ \$486.1707 \$\frac{1}{4}\$ \$565\$ \$\frac{1}{4}\$ \$486.1707 \$\frac{1}{4}\$ \$1665\$ \$\frac{1}{4}\$ \$1665\$ \$\frac{1}{4}\$ \$1665\$ \$\frac{1}{4}\$ \$\frac{1}{	L·3600
\frac{1}{2} 4128·2490 \frac{1}{2} 4839·8198 \frac{1}{2} 560'	7·9392
\frac{1}{8} 4142·4967 \frac{1}{8} 4855·2455 \frac{1}{8} 562455 \frac{1}{8}	1.5430
\$\frac{142.4967}{4156.7689}	1.1714
$\frac{1}{3}$ 4171·0656 $\frac{7}{3}$ 4886·1707 $\frac{7}{3}$ 565	7·8 2 36
73 in. 4185·3868 79 in. 4901·6669 85 in. 5674	L·5017
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2037
\frac{1}{2} \begin{pmatrix} 4214 \cdot 1029 \end{pmatrix} \frac{1}{2} \begin{pmatrix} 4932 \cdot 7423 \end{pmatrix} \frac{1}{2} \begin{pmatrix} 570' \end{pmatrix}	7.9302
\$ 4228·4979 \$ 4948·3154 \$ 5724	1.6814
1 4242·9171 1 4963·9127 1 574	4569
4 4257:3611 4 4979:5310 4 575	3.2631
4271-8296 4 4295-1814 4 577	0818
1 4	9311
74 in. 4300·8404 80 in. 5026·5482 86 in. 5806	3·8048
	5.7032
1 3 6 6	2.6260
	5735
\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	3·5454
4373.7967 4 5105.3948 4 5893	3.5420
4 4373·7967	0.5630
	7·6087
	Ŀ 67 87
\frac{1}{8}	·7734
$\frac{1}{4}$ 4447·3662 $\frac{1}{4}$ 5184·8551 $\frac{1}{4}$ 5978	3·8 926
\$\frac{3}{8} 4462\cdot 1539 \$\frac{3}{8} 5200\cdot 8208 \$\frac{3}{8} 5990	S·0365
1 4447:3662 1 5184:8551 1 5976 2 4462:1539 1 5200:8208 1 5996 3 4476:9659 1 5216:8109 1 601 4 4491:8026 1 5232:8258 1 603 3 4506:6637 1 5248:8650 1 604 4 4521:5495 1 5264:9289 1 606	3·2047
\frac{1}{2})·3975
4506.6637 4 5248.8650 4 604	7·6149
\$\frac{4432\cdot 6032}{4447\cdot 3662}\$ \$\frac{1}{4}\$ \$\frac{5168\cdot 9140}{5184\cdot 8551}\$ \$\frac{1}{4}\$ \$\frac{597}{4}\$ \$\frac{1}{8}\$ \$\frac{4462\cdot 1539}{4}\$ \$\frac{1}{8}\$ \$\frac{5900\cdot 8208}{8}\$ \$\frac{1}{8}\$ \$\frac{599}{4}\$ \$\frac{1}{4}\$ \$\frac{4476\cdot 9659}{4}\$ \$\frac{1}{8}\$ \$\frac{5216\cdot 8109}{4}\$ \$\frac{1}{8}\$ \$\frac{601\cdot 6037}{4}\$ \$\frac{1}{8}\$ \$\frac{4506\cdot 6637}{4}\$ \$\frac{1}{8}\$ \$\frac{5248\cdot 8650}{4}\$ \$\frac{1}{8}\$ \$\frac{604\cdot 6037}{4}\$ \$\frac{1}{8}\$ \$\frac{4521\cdot 5495}{4}\$ \$\frac{1}{8}\$ \$\frac{5264\cdot 9289}{4}\$ \$\frac{1}{8}\$ \$\frac{606\cdot 6037}{4}\$	Ŀ 8569
76 in. 4536·4598 82 in. 5281·0172 88 in. 608	2·1234
	9.4145
	5·7300
4581.3379 5329.4297 613	1.0702
1 4596·3464 1 5345·6162 1 615	l· 4 349
4611-3895 5361-8273 616	3·8 24 0
\$\frac{3}{8}\$ 4581·3379 \$\frac{3}{8}\$ 5329·4297 \$\frac{3}{8}\$ 613-\\ \$\frac{1}{2}\$ 4596·3464 \$\frac{1}{2}\$ 5345·6162 \$\frac{1}{2}\$ 615-\\ \$\frac{3}{8}\$ 4611·3895 \$\frac{1}{8}\$ 5361·8273 \$\frac{3}{8}\$ 616-\\ \$\frac{3}{4}\$ 4626·4370 \$\frac{3}{4}\$ 5378·0630 \$\frac{3}{4}\$ 618-\\ \$\frac{1}{4}\$ 4641·5192 \$\frac{1}{4}\$ 5394·3233 \$\frac{7}{4}\$ 620-\\ \$\frac{3}{4}\$ 626-\\ \$\frac{3}{4}\$	5·2377
4 4566·3540 4 5313·2677 4 6110 3 4581·3379 3 5329·4297 3 613 4 4596·3464 4 5345·6162 4 615 4 4611·3895 4 5361·8273 616 4 4626·4370 4 5378·0630 4 618 3 4641·5192 3 5394·3233 3 620	3.6751

889 93 863 882 466 156 156 1112 1113 1660 151 199 173 183 184 185 185 185 185 185 185 185 185	6811·181 6829·478 6847·800 6866·147 6884·518 6902·913 6921·333 in. 6939·778	4 8 14 15 17 17 17 17 17 17 17	7389·8113 7408·8695 7427·9522 7447·0595 7466·1913 7485·3478 7504·5285 7523·7340
1882 146 156	6829-478 6847-800 6866-147 6884-518 6902-913 6921-333 in. 6939-778	1	7427-9522 7447-0595 7466-1913 7485-3478 7504-5285
146 156 112 113 1660 251 94	6847.800 6866.147 6884.518 6902.913 6921.333	12 \$\frac{3}{5} \\ \frac{3}{5} \\ \frac{1}{5} \\	7447·0595 7466·1913 7485·3478 7504·5285
251 94 969 4	in. 6939·778	"	7466·1913 7485·3478 7504·5285
251 94 969 4	in. 6939·778	"	7485·3478 7504·5285
251 94 969 4	in. 6939·778	"	7504.5285
251 94 969 4	in. 6939·778	"	
251 94 969 4	in. 6939·778	"	7523.7340
69		. 11	ı
II 9		2 98 in.	7542-9640
	6958-247	4	7562-2186
no II		4 0 3 9 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	7581.4976
l99	6995-259	3 👸	7600-8012
)73	7013.801	9 🔒	7620.1293
93 🚪	7032-369	3 8	7639.4810
54 4	7050-961	2 4	7658.8593
65 4	7069-577	7 7	7678-2610
21 95	in. 7088-218	4 99 in.	7697:6874
22 }	7106 ·883	9 1	7717.1383
69	7125.579	9 1	7736.6137
662 198 181 108	7144-288	- 11 0	7756.1137
.9 8 ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅ ⋅	} 7163·027	6 🙀	7775.6382
81 {	7181.791	4 🛊	7795.1873
808 4	7260.579	4 4	7814.7608
82	7219-392	1 7	7834-3590
00 96	in. 7238·229	5 100 in.	7853-9816
65	7257.091	- 11	1
375	7275.977	7	
31 1	7294.888		
	7313.824		
30 🖠	7332.784		
330 	7351.768		
330 8 377 8 368 8	ł 7370·777	7	
	75 '	175	75 7975,0777



CATALOG

Practical and Scientific Books

PUBLISHED BY

HENRY CAREY BAIRD & CO.

INDUSTRIAL PUBLISHERS, BOOKSELLERS AND IMPORTERS,

810 Walnut Street, Philadelphia.

- Any of the Books comprised in this Catalogue will be sent by mail, free of postage, to any address in the world, at the publication prices,
- A Descriptive Catalogue, 96 pages, 8vo., will be sent free and free of postage, to any one in any part of the world, who will furnish his address.
- Where not otherwise stated, all of the Books in this Catalogue are bound in muslin.

AMATEUR MECHANICS' WORKSHOP:

ANDRES.—A Practical Treatise on the Fabrication of Volatile and Fat Varnishes, Lacquers, Siccatives and Sealing

From the German of Erwin Andres, Manufacturer of Varnishes and Lacquers. With additions on the Manufacture and Application of Varnishes, Stains for Wood, Horn, Ivory, Bone and Leather. From the German of Dr. EMIL WINCKLER and Louis E. ANDES. The whole translated and edited by WILLIAM T. BRANNT. With II illustrations. - 12mo.

ARLOT.—A Complete Guide for Coach Painters:
Translated from the French of M. ARLOT, Coach Painter; for eleven years Foreman of Painting to M. Eherler, Coach Maker, Paris. By A. A. FESQUET, Chemist and Engineer. To which is added an Appendix, containing Information respecting the Materials and the Practice of Coach and Car Painting and Varnishing in the United States and Great Britain. 12mo. \$1.25

ARMENGAUD, AMOROUX, AND JOHNSON.—The Practical Draughtsman's Book of Industrial Design, and Machinist's and Engineer's Drawing Companion:

ARMSTRONG.—The Construction and Management of Steam Boilers:

By R. Armstrong, C. E. With an Appendix by ROBERT MALLET, C. E., F. R. S. Seventh Edition. Illustrated. 1 vol. 12mo. 75

ARROWSMITH.—Paper-Hanger's Companion:

ASHTON.—The Theory and Practice of the Art of Designing Fancy Cotton and Woollen Cloths from Sample:

Giving full instructions for reducing drafts, as well as the methods of spooling and making out harness for cross drafts and finding any required reed; with calculations and tables of yarn. By FREDERIC T. ASHTON, Designer, West Pittsfield, Mass. With fifty-two illustrations. One vol. folio

AUERBACH-CROOKES.-Anthracen:

BAIRD.—Miscellaneous Papers on Economic Questions. By Henry Carey Baird. (In preparation.)

BAIRD.—The American Cotton Spinner, and Manager's and Carder's Guide:

A Practical Treatise on Cotton Spinning; giving the Dimensions and Speed of Machinery, Draught and Twist Calculations, etc.; with notices of recent Improvements: together with Rules and Examples for making changes in the sizes and numbers of Roving and Yarn, Compiled from the papers of the late ROBERT H. BAIRD. 12mo.

\$1.50

\$2.25

BAIRD.—Standard Wages Computing Tables: An Improvement in all former Methods of Computation, so arranged that wages for days, hours, or fractions of hours, at a specified rate per day or hour, may be ascertained at a glance. By T. SPANGLER BAIRD. Oblong folio \$5.00 BAKER.—Long-Span Railway Bridges: Comprising Investigations of the Comparative Theoretical and Practical Advantages of the various Adopted or Proposed Type Systems of Construction; with numerous Formulæ and Tables. B. BAKER. 12mo. \$1.50 BAKER.—The Mathematical Theory of the Steam-Engine: With Rules at length, and Examples worked out for the use of Practical Men. By T. BAKER, C. E., with numerous Diagrams. Sixth Edition, Revised by Prof. J. R. Young. 12mo. BARLOW.—The History and Principles of Weaving, by Hand and by Power: Reprinted, with Considerable Additions, from "Engineering," with a chapter on Lace-making Machinery, reprinted from the Journal of the "Society of Arts." By ALFRED BARLOW. With several hundred Including descriptions of various mechanical devices for the Economic Generation of Heat by the Combustion of Fuel, whether solid, liquid or gaseous. 8vo. . BARR.—A Practical Treatise on High Pressure Steam Boilers: Including Results of Recent Experimental Tests of Boiler Materials, together with a Description of Approved Safety Apparatus, Steam Pumps, Injectors and Economizers in actual use. By Wm. M. BARR. 204 Illustrations. 8vo. \$3.00 BAUERMAN.—A Treatise on the Metallurgy of Iron: Containing Outlines of the History of Iron Manufacture, Methods of Assay, and Analysis of Iron Ores, Processes of Manufacture of Iron and Steel, etc., etc. By H. BAUERMAN, F. G. S., Associate of the Royal School of Mines. Fifth Edition, Revised and Enlarged. Illustrated with numerous Wood Engravings from Drawings by J. B. JORDAN. 12mo. \$2.00 BAYLES.—House Drainage and Water Service: In Cities, Villages and Rural Neighborhoods. With Incidental Consideration of Certain Causes Affecting the Healthfulness of Dwellings. By JAMES C. BAYLES, Editor of "The Iron Age" and "The Metal Worker." With numerous illustrations. 8vo. cloth, \$3.00 BEANS.-A Treatise on Railway Curves and Location of Railroads: By E. W. BEANS, C. E. Illustrated. 12mo. Tucks BECKETT.—A Rudimentary Treatise on Clocks, and Watches and Bells: By Sir EDMUND BECKETT, Bart., LL. D., Q. C. F. R. A. S. With numerous illustrations. Seventh Edition, Revised and Enlarged.

BELL.—Carpentry Made Easy:
Or, The Science and Art of Framing on a New and Improved
System. With Specific Instructions for Building Balloon Frames, Barn
Frames, Mill Frames, Warehouses, Church Spires, etc. Comprising
also a System of Bridge Building, with Bills, Estimates of Cost, and
valuable Tables. Illustrated by forty-four plates, comprising aearly
200 figures. By WILLIAM E. BELL, Architect and Practical Builder.
8vo
BEMROSE.—Fret-Cutting and Perforated Carving:
With fifty-three practical illustrations. By W. BEMROSE, JR. I vol.
quarto
BEMROSE.—Manual of Buhl-work and Marquetry:
With Practical Instructions for Learners, and ninety colored designs.
By W. Bemrose, Jr. 1 vol. quarto \$3.00
BEMROSE.—Manual of Wood Carving:
With Practical Illustrations for Learners of the Art, and Original and
Selected Designs Ry WILLIAM REMPOSE IR With an Intro.
Selected Designs. By WILLIAM BEMROSE, JR. With an Introduction by LLEWELLYN JEWITT, F. S. A., etc. With 128 illustra-
tions, 4to
BILLINGS.—Tobacco:
Its History, Variety, Culture, Manufacture, Commerce, and Various
Modes of Use. By E. R. BILLINGS. Illustrated by nearly 200
engravings. 8vo
BIRD.—The American Practical Dyers' Companion:
Comprising a Description of the Principal Dye-Stuffs and Chemicals
used in Dyeing, their Natures and Uses; Mordants, and How Made;
with the best American, English, French and German processes for
Bleaching and Dyeing Silk, Wool, Cotton, Linen, Flannel, Felt,
Dress Goods, Mixed and Hosiery Yarns, Feathers, Grass, Felt, Fur,
Wool, and Straw Hats, Jute Yarn, Vegetable Ivory, Mats, Skins,
Furs, Leather, etc., etc. By Wood, Aniline, and other Processes,
together with Remarks on Finishing Agents, and Instructions in the
Finishing of Fabrics, Substitutes for Indigo, Water-Proofing of
Materials, Tests and Purification of Water, Manufacture of Aniline
and other New Dye Wares, Harmonizing Colors, etc., etc.; embrac-
ing in all over 800 Receipts for Colors and Shades, accompanied by
170 Dyed Samples of Raw Materials and Fabrics. By F. J. BIRD,
Practical Dyer, Author of "The Dyers' Hand-Book." 8vo. \$10.00
BLINNA Practical Workshop Companion for Tin, Sheet-
Iron, and Copper-plate Workers:
Containing Rules for describing various kinds of Patterns used by
Tin, Sheet-Iron and Copper-plate Workers; Practical Geometry;
Mensuration of Surfaces and Solids; Tables of the Weights of
Metals, Lead-pipe, etc.: Tables of Areas and Circumferences
Metals, Lead-pipe, etc.; Tables of Areas and Circumferences of Circles; Japan, Varnishes, Lackers, Cements, Compositions, etc.,
etc. By LEROY J. BLINN, Master Mechanic. With over One
Hundred Illustrations. 12mo

BOOTH.—Marble Worker's Manual:

Containing Practical Information respecting Marbles in general, their Cutting, Working and Polishing; Veneering of Marble; Mosaics; Composition and Use of Artificial Marble, Stuccos, Cements, Receipts, Secrets, etc., etc. Translated from the French by M. L. Booth. With an Appendix concerning American Marbles. 12mo., cloth \$1.50 BOOTH and MORFIT.—The Encyclopædia of Chemistry,

Practical and Theoretical:

Embracing its application to the Arts, Metallurgy, Mineralogy, Geology, Medicine and Pharmacy. By James C. Booth, Melter and Refiner in the United States Mint, Professor of Applied Chemistry in the Franklin Institute, etc., assisted by Campbell Morfit, author of "Chemical Manipulations," etc. Seventh Edition. Complete in one volume, royal 8vo., 978 pages, with numerous wood-cuts and other illustrations \$5.00

BRAMWELL.—The Wool Carder's Vade-Mecum:

BRANNT.—A Practical Treatise on the Raw Materials and the Distillation and Rectification of Alcohol, and the Preparation of Alcoholic Liquors, Liqueurs, Cordials, Bitters, etc.: Edited chiefly from the German of Dr. K. Stammer, Dr. F. Elsner, and E. Schubert. By Wm. T. Brannt. Illustrated by thirty-one engravings. 12mo. \$2.50

BRANNT—WAHL.—The Techno-Chemical Receipt Book:
Containing several thousand Receipts covering the latest, most important, and most useful discoveries in Chemical Technology, and their Practical Application in the Arts and the Industries. Edited chiefly from the German of Drs. Winckler, Elsner, Heintze, Mierzinski, Jacobsen, Koller, and Heinzerling, with additions by WM. T. BRANNT and WM. H. WAHL, PH. D. Illustrated by 78 engravings. 12mo. 495 pages \$2.00

12mo. 495 pages

BROWN.—Five Hundred and Seven Mechanical Movements.

Embracing all those which are most important in Dynamics, Hydraulics, Hydrostatics, Pneumatics, Steam-Engines, Mill and other Gearing, Presses, Horology and Miscellaneous Machinery; and including many movements never before published, and several of which have only recently come into use. By HENRY T. BROWN 12mo.

BULLOCK.—The American Cottage Builder:

A Series of Designs, Plans and Specifications, from \$200 to \$20,000, for Homes for the People; together with Warming, Ventilation, Drainage, Painting and Landscape Gardening. By JOHN BULLOCK, Architect and Editor of "The Rudiments of Architecture and Building," etc., etc. Illustrated by 75 engravings. 8vo. \$3.50 BULLOCK.—The Rudiments of Architecture and Building:

BULLOCK.—The Rudiments of Architecture and Building:
For the use of Architects, Builders, Draughtsmen, Machinists, Engineers and Mechanics. Edited by John Bullock, author of "The American Cottage Builder." Illustrated by 250 Engravings. 8vo. \$3.50

BURGH .-- Practical Rules for the Proportions of Modern Engines and Boilers for Land and Marine Purposes. \$1.50

By N. P. Burgh, Engineer. 12mo.

BURNS.—The American Woolen Manufacturer:

A Practical Treatise on the Manufacture of Woolens, in two parts. Part First gives full and explicit instructions upon Drafting, Cross-Drawing, Combining Weaves, and the correct arrangement of Weights. Colors and Sizes of Yarns to produce any desired fabric. Illustrated with diagrams of various weavings, and twelve samples of cloth for explanation and practice. Part Second is fully supplied with extended Tables, Rules, Examples, Explanations, etc.; gives full and practical information, in detailed order, from the stock department to the market, of the proper selection and use of the various grades and staples of wool, with the admixture of waste, cotton and shoddy; and the proper application and economical use of the various oils, drugs, dye stuffs, soaps, belting, etc. Also, the most approved method for Calculating and Estimating the Cost of Goods, for all Wool, Wool Waste and Cotton and Cotton Warps. With Examples and Calculations on the Circular motions of Wheels, Pinions, Drums, Pulleys and Gears, how to speed them, etc. The two parts combined form a whole work on the American way of manufacturing more complete than any yet issued. By GEORGE C. BURNS. 8vo.

BYLES.—Sophisms of Free Trade and Popular Political Economy Examined.

By a BARRISTER (SIR JOHN BARNARD BYLES, Judge of Common

From the Ninth English Edition, as published by the Manchester Reciprocity Association. 12mo. \$1.25 BOWMAN.—The Structure of the Wool Fibre in its Relation

to the Use of Wool for Technical Purposes: Being the substance, with additions, of Five Lectures, delivered at

the request of the Council, to the members of the Bradford Technical College, and the Society of Dyers and Colorists. By F. H. Bow-MAN, D. Sc., F. R. S. E., F. L. S. Illustrated by 32 engravings.

BYRN.—The Complete Practical Distiller:

Comprising the most perfect and exact Theoretical and Practical Description of the Art of Distillation and Rectification; including all of the most recent improvements in distilling apparatus; instructions for preparing spirits from the numerous vegetables, fruits, etc; directions for the distillation and preparation of all kinds of brandies and other spirits, spirituous and other compounds, etc. By M. LA FAYETTE Byrn, M. D. Eighth Edition. To which are added Practical Directions for Distilling, from the French of Th. Fling, Brewer and Distiller. 12mo.

BYRNE.—Hand-Book for the Artisan, Mechanic, and Engineer:

Comprising the Grinding and Sharpening of Cutting Tools, Abrasive Processes, Lapidary Work, Gem and Glass Engraving, Varnishing and Lackering, Apparatus, Materials and Processes for Grinding and Polishing, etc. By OLIVER BYRNE. Illustrated by 185 wood engravings. 8vo. \$5.00

BYRNE.—Pocket-Book for Railroad and Civil Engineers:
Containing New, Exact and Concise Methods for Laying out Railroad
Curves, Switches, Frog Angles and Crossings; the Staking out of
work; Levelling; the Calculation of Cuttings; Embankments; Earthwork, etc. By OLIVER BYRNE. 18mo., full bound, pocket-book
form
\$1.75
BYRNE.—The Practical Metal-Worker's Assistant:

Comprising Metallurgic Chemistry; the Arts of Working all Metals and Alloys; Forging of Iron and Steel; Hardening and Tempering; Melting and Mixing; Casting and Founding; Works in Sheet Metal; the Processes Dependent on the Ductility of the Metals; Soldering; and the most Improved Processes and Tools employed by Metal-Workers. With the Application of the Art of Electro-Metallurgy to Manufacturing Processes; collected from Original Sources, and from the works of Holtzapffel, Bergeron, Leupold, Plumier, Napier, Scoffern, Clay, Fairbairn and others. By OLIVER BYRNE. A new,

revised and improved edition, to which is added an Appendix, containing The Manufacture of Russian Sheet-Iron. By JOHN PERCY, M. D., F. R. S. The Manufacture of Malleable Iron Castings, and Improvements in Bessemer Steel. By A. A. FESQUET, Chemist and Engineer. With over Six Hundred Engravings, Illustrating every

For the Engineer, Mechanic, Manufacturer of Engine Work, Nava, Architect, Miner and Millwright. By OLIVER BYRNE. 8vo., nearly 600 pages \$4.50

CABINET MAKER'S ALBUM OF FURNITURE:

CALLINGHAM.—Sign Writing and Glass Embossing:

A Complete Practical Illustrated Manual of the Art. By I

A Complete Practical Illustrated Manual of the Art. By JAMES CALLINGHAM. 12mo. \$1.50 CAMPIN.—A Practical Treatise on Mechanical Engineering:

Comprising Metallurgy, Moulding, Casting, Forging, Tools, Workshop Machinery, Mechanical Manipulation, Manufacture of Steam-Engines, etc. With an Appendix on the Analysis of Iron and Iron Ores. By Francis Campin, C. E. To which are added, Observations on the Construction of Steam Boilers, and Remarks upon Furnaces used for Smoke Prevention; with a Chapter on Explosions. By R. Armstrong, C. E., and John Bourne. Rules for Calculating the Change Wheels for Screws on a Turning Lathe, and for a Wheel cutting Machine. By J. La Nicca. Management of Steel, Including Forging, Hardening, Tempering, Annealing, Shrinking and Expansion; and the Case-hardening of Iron. By G. Ede. 8vo. Illustrated with twenty-nine plates and 100 wood engravings \$5.00

CAREY.—A Memoir of Henry C. Carey.
By Dr. Wm. Elder. With a portrait. 8vo., cloth 75
CAREY.—The Works of Henry C. Carey:
Harmony of Interests: Agricultural, Manufacturing and Commer-
cial. 8vo
Manual of Social Science. Condensed from Carey's "Principles
of Social Science." By KATE MCKEAN. I vol. 12mo \$2.25
Miscellaneous Works. With a Portrait. 2 vols. 8vo. \$6.00
Past, Present and Future. 8vo \$2.50
Principles of Social Science. 3 volumes, 8vo \$10.00
The Slave-Trade, Domestic and Foreign; Why it Exists, and
How it may be Extinguished (1853). 8vo \$2.00
The Unity of Law: As Exhibited in the Relations of Physical,
Social, Mental and Moral Science (1872). 8vo \$3.50
CLARK.—Tramways, their Construction and Working:
Embracing a Comprehensive History of the System. With an ex-
haustive analysis of the various modes of traction, including horse-
power, steam, heated water and compressed air; a description of the
varieties of Rolling stock, and ample details of cost and working ex-
penses. By D. KINNEAR CLARK. Illustrated by over 200 wood
engravings, and thirteen folding plates. 2 vols. 8vo \$12.50
COLBURN.—The Locomotive Engine:
Including a Description of its Structure, Rules for Estimating its
Capabilities, and Practical Observations on its Construction and Man-
agement. By ZERAH COLBURN. Illustrated. 12mo \$1.00
COLLENS.—The Eden of Labor; or, the Christian Utopia.
By T. WHARTON COLLENS, author of "Humanics," "The History of Charity," etc. 12mo. Paper cover, \$1.00; Cloth . \$1.25
of Charity," etc. 12mo. Paper cover, \$1.00; Cloth . \$1.25 COOLEY.—A Complete Practical Treatise on Perfumery:
Being a Hand-book of Perfumes, Cosmetics and other Toilet Articles.
With a Comprehensive Collection of Formulæ. By Arnold J.
COOLEY. 12mo
COOPER.—A Treatise on the use of Belting for the Trans-
mission of Power.
With numerous illustrations of approved and actual methods of ar-
ranging Main Driving and Quarter Twist Belts, and of Belt Fasten-
ings. Examples and Rules in great number for exhibiting and cai-
culating the size and driving power of Belts. Plain, Particular and
Practical Directions for the Treatment, Care and Management of
Belts. Descriptions of many varieties of Beltings, together with
chapters on the Transmission of Power by Ropes; by Iron and
Wood Frictional Gearing; on the Strength of Belting Leather; and
on the Experimental Investigations of Morin, Briggs, and others. By
JOHN H. COOPER, M. E. 8vo
CRAIK.—The Practical American Millwright and Miller.
By DAVID CRAIK, Millwright. Illustrated by numerous wood en-
gravings and two folding plates. 8vo

CRISTIANI.—A Technical Treatise on Soap and Candles:

With a Glance at the Industry of Fats and Oils. By R. S. CRISTIANI, Chemist. Author of "Perfumery and Kindred Arts." Illustrated by 176 engravings. 581 pages, 8vo. \$7.50

CRISTIANI.—Perfumery and Kindred Arts:

A Comprehensive Treatise on Perfumery, containing a History of Perfumes from the remotest ages to the present time. A complete detailed description of the various Materials and Apparatus used in the Perfumer's Art, with thorough Practical Instruction and careful Formulæ, and advice for the fabrication of all known preparations of the day, including Essences, Tinctures, Extracts, Spirits, Waters, Vinegars, Pomades, Powders, Paints, Oils, Emulsions, Cosmetics, Infusions, Pastilles, Tooth Powders and Washes, Cachous, Hair Dyes, Sachets, Essential Oils, Flavoring Extracts, etc.; and full details for making and manipulating Fancy Toilet Soaps, Shaving Creams, etc., by new and improved methods. With an Appendix giving hints and advice for making and fermenting Domestic Wines, Cordials, Liquors, Candies, Jellies, Syrups, Colors, etc., and for Perfuming and Flavoring Segars, Snuff and Tobacco, and Miscellaneous Receipts for various useful Analogous Articles. By R. S. CRISTIANI, Consulting Chemist and Perfumer, Philadelphia. 8vo. \$5.00

CUPPER .- The Universal Stair-Builder:

Being a new Treatise on the Construction of Stair-Cases and Hand-Rails; showing Plans of the various forms of Stairs, method of Placing the Risers in the Cylinders, general method of describing the Face Moulds for a Hand-Rail, and an expeditious method of Squaring the Rail. Useful also to Stonemasons constructing Stone Stairs and Hand-Rails; with a new method of Sawing the Twist Part of any Hand-Rail square from the face of the plank, and to a parallel width. Also, a new method of forming the Easings of the Rail by a gauge; preceded by some necessary Problems in Practical Geometry, with the Sections of Prismatic Solids. Illustrated by 29 plates. By R. A. Cupper, Architect, author of "The Practical Stair-Builder's Guide." Third Edition. Large 4to.

DAVIDSON.—A Practical Manual of House Painting, Grain-

ing, Marbling, and Sign-Writing:

Containing full information on the processes of House Painting in Oil and Distemper, the Formation of Letters and Practice of Sign-Writing, the Principles of Decorative Art, a Course of Elementary Drawing for House Painters, Writers, etc., and a Collection of Useful Receipts. With nine colored illustrations of Woods and Marbles, and numerous wood engravings. By Ellis A. Davidson. 12mo.

#3.c

DAVIES.—A Treatise on Earthy and Other Minerals and Mining:

DAVIES .- A Treatise on Metalliferous Minerals and Mining: By D. C. DAVIES, F. G. S., Mining Engineer, Examiner of Mines, Quarries and Collieries. Illustrated by 148 engravings of Geological Formations, Mining Operations and Machinery, drawn from the practice of all parts of the world. 2d Edition, 12mo., 450 pages \$5.00 DAVIES.—A Treatise on Slate and Slate Quarrying: Scientific, Practical and Commercial. By D. C. DAVIES, F. G. S.,

Mining Engineer, etc. With numerous illustrations and folding plates. 12mo.

DAVIS.—A Practical Treatise on the Manufacture of Bricks, Tiles, Terra-Cotta, etc.:

Including Common, Pressed, Ornamentally Shaped, and Enamelled Bricks, Drain-Tiles, Straight and Curved Sewer-Pipes, Fire-Clays, Fire-Bricks, Terra-Cotta, Roofing-Tiles, Flooring-Tiles, Art-Tiles, Mosaic Plates, and Imitation of Intarsia or Inlaid Surfaces; comprising every important Product of Clay employed in Architecture, Engineering, the Blast-Furnace, for Retorts, etc., with a History and the Actual Processes in Handling, Disintegrating, Tempering, and Moulding the Clay into Shape, Drying Naturally and Artificially, Setting and Burning, Enamelling in Polychrome Colors, Composition and Application of Glazes, etc.; including Full Detailed Descriptions of the most modern Machines, Tools, Kilns, and Kiln-Roofs used. By CHARLES THOMAS DAVIS. Illustrated by 228 Engravings and 6 Plates. 8vo., 472 pages

DAVIS.—The Manufacture of Leather:

Being a description of all of the Processes for the Tanning, Tawing, Currying, Finishing and Dyeing of every kind of Leather; including the various Raw Materials and the Methods for Determining their Values; the Tools, Machines, and all Details of Importance conneoted with an Intelligent and Profitable Prosecution of the Art, with Special Reference to the Best American Practice. To which are added Complete Lists of all American Patents for Materials, Processes, Tools, and Machines for Tanning, Currying, etc By CHARLES THOMAS DAVIS. Illustrated by 302 engravings and 12 Samples of Dyed Leathers. One vol., 8vo., 824 pages \$10.00

DAWIDOWSKY-BRANNT .- A Practical Treatise on the Raw Materials and Fabrication of Glue, Gelatine, Gelatine Veneers and Foils, Isinglass, Cements, Pastes, Mucilages,

Based upon Actual Experience. By F. DAWIDOWSKY, Technical Chemist. Translated from the German, with extensive additions, including a description of the most Recent American Processes, by WILLIAM T. BRANNT, Graduate of the Royal Agricultural College \$2.50

Being a Plain Practical System of Hand-Railing, embracing all its necessary Details, and Geometrically Illustrated by twenty-two Steel Engravings; together with the use of the most approved principles of Practical Geometry. By SIMON DE GRAFF, Architect.

\$2.50

DE KONINCK-DIETZ.-A Practical Manual of Chemical Analysis and Assaying:

As applied to the Manufacture of Iron from its Ores, and to Cast Iron, Wrought Iron, and Steel, as found in Commerce. By L. L. DE KONINCK, Dr. Sc., and E. DIETZ, Engineer. Edited with Notes, by ROBERT MALLET, F. R. S., F. S. G., M. I. C. E., etc. American Edition, Edited with Notes and an Appendix on Iron Ores, by A. A. FESQUET, Chemist and Engineer. 12mo.

DUNCAN.—Practical Surveyor's Guide:

Containing the necessary information to make any person of common capacity, a finished land surveyor without the aid of a teacher. By Andrew Duncan. Illustrated. 12mo. . \$1.25

DUPLAIS.—A Treatise on the Manufacture and Distillation

of Alcoholic Liquors: Comprising Accurate and Complete Details in Regard to Alcohol from Wine, Molasses, Beets, Grain, Rice, Potatoes, Sorghum, Asphodel, Fruits, etc.; with the Distillation and Rectification of Brandy, Whiskey, Rum, Gin, Swiss Absinthe, etc., the Preparation of Aromatic Waters, Volatile Oils or Essences, Sugars, Syrups, Aromatic Tinctures, Liqueurs, Cordial Wines, Effervescing Wines, etc., the Ageing of Brandy and the improvement of Spirits, with Copious Directions and Tables for Testing and Reducing Spirituous Liquors, etc., etc. Translated and Edited from the French of MM. DUPLAIS, Ainè et Jeune. By M. McKennie, M. D. To which are added the United States Internal Revenue Regulations for the Assessment and Collection of Taxes on Distilled Spirits. Illustrated by fourteen folding plates and several wood engravings. 743 pp. 8vo. \$10 00

DUSSAUCE.-A General Treatise on the Manufacture of Vinegar:

Theoretical and Practical. Comprising the various Methods, by the Slow and the Quick Processes, with Alcohol, Wine, Grain, Malt, Cider, Molasses, and Beets; as well as the Fabrication of Wood Vinegar, etc., etc. By Prof. H. Dussauce. 8vo.

DUSSAUCE.—Practical Treatise on the Fabrication of Matches, Gun Cotton, and Fulminating Powder. \$3 OU

By Professor H. Dussauce. 12mo. DYÉR AND COLOR-MAKER'S COMPANION:

Containing upwards of two hundred Receipts for making Colors, on the most approved principles, for all the various styles and fabrics now in existence; with the Scouring Process, and plain Directions for Preparing, Washing-off, and Finishing the Goods. 12mo.

EDWARDS.—A Catechism of the Marine Steam-Engine,

For the use of Engineers, Firemen, and Mechanics. A Practical Work for Practical Men. By EMORY EDWARDS, Mechanical Engineer. Illustrated by sixty-three Engravings, including examples of the most modern Engines. Third edition, thoroughly revised, with much additional matter. 12 mo. 414 pages

EDWARDS.-Modern American Locomotive Engines,

Their Design, Construction and Management. By EMORY EDWARDS. Illustrated 12mo. .

EDWARDS.—Modern American Marine Engines, Boilers, and Screw Propellers.
Their Design and Construction. Showing the Present Practice of
the most Eminent Engineers and Marine Engine Builders in the
United States. Illustrated by 30 large and elaborate plates, 4to. \$5.00 EDWARDS.—The Practical Steam Engineer's Guide
In the Design, Construction, and Management of American Stationary,
Portable, and Steam Fire-Engines, Steam Pumps, Boilers, Injectors,
Governors, Indicators, Pistons and Rings, Safety Valves and Steam
Gauges. For the use of Engineers, Firemen, and Steam Users. By
EMORY EDWARDS. Illustrated by 119 engravings. 420 pages.
I2mo
ELDER.—Conversations on the Principal Subjects of Political
Economy.
By Dr. William Elder. 8vo
ELDER.—Questions of the Day,
Economic and Social. By Dr. WILLIAM ELDER. 8vo \$3 00
ELDER.—Memoir of Henry C. Carey.
By Dr. William Elder. 8vo. cloth
ERNI.—Mineralogy Simplified.
Easy Methods of Determining and Classifying Minerals, including
Ores, by means of the Blowpipe, and by Humid Chemical Analysis,
based on Professor von Kobell's Tables for the Determination of
Minerals, with an Introduction to Modern Chemistry. By HENRY
ERNI, A.M., M.D., Professor of Chemistry. Second Edition, rewritten,
enlarged and improved. 12mo
FAIRBAIRN.—The Principles of Mechanism and Machinery
of Transmission
Comprising the Principles of Mechanism, Wheels, and Pulleys,
Strength and Proportions of Shafts, Coupling of Shafts, and Engag-
ing and Disengaging Gear. By SIR WILLIAM FAIRBAIRN, Bart.
C. E. Beautifully illustrated by over 150 wood-cuts. In one
volume, 12mo. \$2.50
FITCH.—Bessemer Steel,
Ores and Methods, New Facts and Statistics Relating to the Types
of Machinery in Use, the Methods in Vogue, Cost and Class of Labor
employed, and the Character and Availability of the Ores utilized in
the Manufacture of Bessemer Steel in Europe and in the United States;
together with opinions and excerpts from various accepted authorities.
Compiled and arranged by Thomas W. Fitch. 8vo \$3 00
FLEMING.—Narrow Gauge Railways in America.
A Sketch of their Rise, Progress, and Success. Valuable Statistics
as to Grades, Curves, Weight of Rail, Locomotives, Cars, etc. By
HOWARD FLEMING. Illustrated, 8vo \$1 50
FORSYTH.—Book of Designs for Headstones, Mural, and
other Monuments:
Containing 78 Designs. By JAMES FORSYTH. With an Introduction
by Charles Boutell, M. A. 4 to., cloth \$5 00

FRANKEL—HUTTER.—A Practical Treatise on the Manufacture of Starch, Glucose, Starch-Sugar, and Dextrine: Based on the German of LADISLAUS VON WAGNER, Professor in the Royal Technical High School, Buda-Pest, Hungary, and other authorities. By JULIUS FRANKEL, Graduate of the Polytechnic School of Hanover. Edited by ROBERT HUTTER, Chemist, Practical Manufacturer of Starch-Sugar. Illustrated by 58 engravings, covering every branch of the subject, including examples of the most Recent and Best American Machinery. 8vo., 344 pp.

GEE.—The Goldsmith's Handbook:

Containing full instructions for the Alloying and Working of Gold, including the Art of Alloying, Melting, Reducing, Coloring, Collecting, and Refining; the Processes of Manipulation, Recovery of Waste; Chemical and Physical Properties of Gold; with a New System of Mixing its Alloys; Solders, Enamels, and other Useful Rules and Recipes. By GEORGE E. GEE. 12mo. . \$1.75

GEE.—The Silversmith's Handbook:

Containing full instructions for the Alloying and Working of Silver, including the different modes of Refining and Melting the Metal; its Solders; the Preparation of Imitation Alloys; Methods of Manipulation; Prevention of Waste; Instructions for Improving and Finishing the Surface of the Work; together with other Useful Information and Memoranda. By George E. Gee, Jeweller. Illustrated. 12mo.

\$I.75

GOTHIC ALBUM FOR CABINET-MAKERS:
Designs for Gothic Furniture. Twenty-three plates. Oblong \$2.00

GREENWOOD.—Steel and Iron:

Comprising the Practice and Theory of the Several Methods Pursued in their Manufacture, and of their Treatment in the Rolling-Mills, the Forge, and the Foundry. By WILLIAM HENRY GREEN-WOOD, F. C. S. Asso. M. I. C. E., M. I. M. E., Associate of the Royal School of Mines. With 97 Diagrams, 536 pages. 12mo. .

GREGORY.—Mathematics for Practical Men:

Adapted to the Pursuits of Surveyors, Architects, Mechanics, and Civil Engineers. By OLINTHUS GREGORY. 8vo., plates. \$3.00

GRIER.—Rural Hydraulics:

A Practical Treatise on Rural Household Water Supply. Giving a full description of Springs and Wells, of Pumps and Hydraulic Ram, with Instructions in Cistern Building, Laying of Pipes, etc. By W. W. Grier. Illustrated 8vo.

GRIMSHAW.-Modern Milling:

Being the substance of two addresses delivered by request, at the Franklin Institute, Philadelphia, January 19th and January 27th, 1881. By ROBERT GRIMSHAW, Ph. D. Edited from the Phonographic Reports. With 28 Illustrations. 8vo.

GŘIMSHAW.—Saws:

The History, Development, Action, Classification, and Comparison of Saws of all kinds. With Copious Appendices. Giving the details

the By 2.00 the Enthe En. By 1.75 s of nes. D. 2.50
AW. llus- the the By 2.00 the En- the En- By 1.75 s of nes.
the the By 2.00 the Enthe Enth
the the By 2.00 the gles, Enthe En-By 1.75 s of nes. D. 2.50 ties,
the the By 2.00 the Enthe Ensor of nes. D. 2.50
the By 2.00 the gles, Enthe En-By 1.75 s of nes. D. 2.50 ties,
the By 2.00 the gles, Enthe En-By 1.75 s of nes. D. 2.50 ties,
By 2.00 the gles, Enthe En- By 1.75 s of ness. D. 2.50
the gles, Enthe En- By 1.75 s of nes. D. 2.50
gles, Enthe EnBy 1.75 s of nes. D. 2.50
gles, En- the En- By 1.75 s of nes. . D. 2.50
Enthe EnBy 1.75 s of nes. D. 2.50
Enthe EnBy 1.75 s of nes. D. 2.50
the En- By 1.75 s of nes. D. 2.50
En- By 1.75 s of nes. D. 2.50
By 1.75 s of nes. . D. 2.50
s of nes. D. 2.50
s of nes. D. 2.50
nes. . D. 2.50 ties,
nes. . D. 2.50 ties,
. D. 2.50 ties,
2.50 ties,
ties,
the
ries,
UET,
3.00
ton,
and By
arns
5.00
tter.
I.25
1.23
en n -
ors,
. Т.
ıtta
r of
and
auu
72

	proof Substances, Elastic Tissues, the Utilization of Waste, etc., etc.
	From the German of RAIMUND HOFFER. By W. T. BRANNT.
	Illustrated 12mo
Н	OFMANNA Practical Treatise on the Manufacture of
	Paper in all its Branches:
	By CARL HOFMANN, Late Superintendent of Paper-Mills in Germany
	and the United States, recently Manager of the "Dublic Laders"
	and the United States; recently Manager of the "Public Ledger"
	Paper Mills, near Elkton, Maryland. Illustrated by 110 wood en-
	gravings, and five large Folding Plates. 4to., cloth; about 400
	pages
H	UGHES.—American Miller and Millwright's Assistant:
	By WILLIAM CARTER HUGHES. 12mo \$1.50
H	ULME.—Worked Examination Questions in Plane Geomet-
	rical Drawing:
	For the Use of Candidates for the Royal Military Academy, Wool-
	wich; the Royal Military College, Sandhurst; the Indian Civil En-
	gineering College, Cooper's Hill; Indian Public Works and Tele-
	graph Departments; Royal Marine Light Infantry; the Oxford and
	Cambridge Local Examinations, etc. By F. EDWARD HULME, F. L.
	S., F. S. A., Art-Master Marlborough College. Illustrated by 300
T 1	examples. Small quarto
J	ERVIS.—Railroad Property:
	A Treatise on the Construction and Management of Railways;
	designed to afford useful knowledge, in the popular style, to the
	holders of this class of property; as well as Railway Managers, Offi-
	cers, and Agents. By JOHN B. JERVIS, late Civil Engineer of the
	Hudson River Railroad, Croton Aqueduct, etc. 12mo., cloth \$2.00
K	EENE.—A Hand-Book of Practical Gauging:
	For the Use of Beginners, to which is added a Chapter on Distilla-
	tion, describing the process in operation at the Custom-House for
	ascertaining the Strength of Wines. By JAMES B. KEENE, of H. M.
	Customs. 8vo
K	ELLEY.—Speeches, Addresses, and Letters on Industrial and
	Financial Questions:
	By Hon. William D. Kelley, M. C. 544 pages, 8vo \$3.00
v	ELLOGG.—A New Monetary System:
"	
	The only means of Securing the respective Rights of Labor and
	Property, and of Protecting the Public from Financial Revulsions.
	By EDWARD KELLOGG. Revised from his work on "Labor and
	other Capital." With numerous additions from his manuscript.
	Edited by MARY KELLOGG PUTNAM. Fifth edition. To which is
	added a Biographical Sketch of the Author. One volume, 12mo.
	Paper cover
	Bound in cloth
K	EMLO.—Watch-Repairer's Hand-Book:
	Being a Complete Guide to the Young Beginner, in Taking Apart,
	Putting Together, and Thoroughly Cleaning the English Lever and
	other Foreign Watches, and all American Watches. By F. KEMLO,
	Practical Watchmaker. With Illustrations. 12mo. \$1.25
	Tractical Traccillanci. Tritil Industry P1.23

KENTISH.—A Treatise on a Box of Instruments,

And the Slide Rule; with the Theory of Trigonometry and Logarithms, including Practical Geometry, Surveying, Measuring of Timber, Cask and Malt Gauging, Heights, and Distances. By THOMAS KENTISH. In one volume. 12mo. \$1.25

KERL.—The Assayer's Manual:

An Abridged Treatise on the Docimastic Examination of Ores, and Furnace and other Artificial Products. By Bruno Kerl, Professor in the Royal School of Mines; Member of the Royal Technical Commission for the Industries, and of the Imperial Patent-Office, Berlin. Translated from the German by William T. Brannt, Graduate of the Royal Agricultural College of Eldena, Prussia. Edited by William H. Wahl, Ph. D., Secretary of the Franklin Institute, Phiiadelphia. Illustrated by sixty-five engravings. 8vo.

\$3.00 KINGZETT.—The History, Products, and Processes of the Alkali Trade:

Including the most Recent Improvements. By Charles Thomas Kingzett, Consulting Chemist. With 23 illustrations. 8vo. \$2.50

KINSLEY.—Self-Instructor on Lumber Surveying:

For the Use of Lumber Manufacturers, Surveyors, and Teachers, By CHARLES KINSLEY, Practical Surveyor and Teacher of Surveying, 12mo. \$2.00

KIRK.—The Founding of Metals:

A Practical Treatise on the Melting of Iron, with a Description of the Founding of Alloys; also, of all the Metals and Mineral Substances used in the Art of Founding. Collected from original sources. By EDWARD KIRK, Practical Foundryman and Chemist. Illustrated. Third edition. 8vo. \$2.50

KITTREDGE.—The Compendium of Architectural Sheet-Metal Work:

Profusely Illustrated. Embracing Rules and Directions for Estimates, Items of Cost, Nomenclature, Tables of Brackets, Modillions, Dentals, Trusses, Stop-Blocks, Frieze Pieces, etc. Architect's Specification, Tables of Tin-Roofing, Galvanized Iron, etc., etc. To which is added the Exemplar of Architectural Sheet-Metal Work, containing details of the Centennial Buildings, and other important Sheet-Metal Work, Designs and Prices of Architectural Ornaments, as manufactured for the Trade by the Kittredge Cornice and Ornament Company, and a Catalogue of Cornices, Window-Caps, Mouldings, etc., as manufactured by the Kittredge Cornice and Ornament Company. The whole supplemented by a full Index and Table of Contents. By A. O. KITTREDGE. 8vo., 565 pages

LANDRIN.—A Treatise on Steel:

Comprising its Theory, Metallurgy, Properties, Practical Working, and Use. By M. H. C. LANDRIN, JR., Civil Engineer. Translated from the French, with Notes, by A. A. FESQUET, Chemist and Engineer. With an Appendix on the Bessemer and the Martin Processes for Manufacturing Steel, from the Report of Abram S. Hewitt

United States Commissioner to the Universal Exposition, Paris, 1867.
LARDEN.—A School Course on Heat: By W. LARDEN, M. A. 321 pp. 12mo \$2.00
LARDNER.—The Steam-Engine:
For the Use of Beginners. By DR. LARDNER. Illustrated. 12mo.
A Concise Treatise on Brass Founding, Moulding, the Metals and their Alloys, etc.; to which are added Recent Improvements in the Manufacture of Iron, Steel by the Bessemer Process, etc., etc. By JAMES LARKIN, late Conductor of the Brass Foundry Department in Reany, Neafie & Co.'s Penn Works, Philadelphia. Fifth edition, revised, with extensive additions. 12mo. \$2.25
LEROUX.—A Practical Treatise on the Manufacture of
Worsteds and Carded Yarns: Comprising Practical Mechanics, with Rules and Calculations applied to Spinning; Sorting, Cleaning, and Scouring Wools; the English and French Methods of Combing, Drawing, and Spinning Worsteds, and Manusacturing Carded Yarns. Translated from the French of Charles Leroux, Mechanical Engineer and Superintendent of a Spinning-Mill, by Horatio Paine, M. D., and A. A. Fesquer, Chemist and Engineer. Illustrated by twelve large Plates. To which is added an Appendix, containing Extracts from the Reports of the International Jury, and of the Artisans selected by the Committee appointed by the Council of the Society of Arts, London, on Woolen and Worsted Machinery and Fabrics, as exhibited in the Paris Universal Exposition, 1867. 8vo. *5.00 LEFFEL.—The Construction of Mill-Dams: Comprising also the Building of Race and Reservoir Embankments and Head-Gates, the Measurement of Streams, Gauging of Water Supply, etc. By James Leffel & Co. Illustrated by 58 engravings. 8vo. *\$2.50 LESLIE.—Complete Cookery:
Directions for Cookery in its Various Branches. By MISS LESLIE. Sixtieth thousand. Thoroughly revised, with the addition of New
Receipts. In 12mo., cloth
Or, Practical Directions to Assayers, Miners, and Smelters, for the Tests and Assays, by Heat and by Wet Processes, for the Ores of all the principal Metals, of Gold and Silver Coins and Alloys, and of Coal, etc. By Oscar M. LIEBER. 12mo. \$1.25 LOVE.—The Art of Dyeing, Cleaning, Scouring, and Finishing, on the Most Approved English and French Methods: Being Practical Instructions in Dyeing Silks, Woolens, and Cottons, Feathers, Chips, Straw, etc. Scouring and Cleaning Bed and Window Curtains, Carpets, Rugs, etc. French and English Cleaning, any Color or Fabric of Silk, Satin, or Damask. By Thomas Love, Working Dyer and Scourer. Second American Edition, to which

	_
	/o.
343 pages	00
Embracing Descriptions of the various Mechanical Appliances us	-4
in the Manufacture of Wood, Metai, and other Substances. 12mo.	
\$1.	75
LUKIN.—The Boy Engineers:	
What They Did, and How They Did It. With 30 plates. 18mo.	
\$1.	75
LUKIN.—The Young Mechanic:	• •
Practical Carpentry. Containing Directions for the Use of all kin	ds
of Tools, and for Construction of Steam-Engines and Mechanic	
Models, including the Art of Turning in Wood and Metal. By Joi	
LUKIN, Author of "The Lathe and Its Uses," etc. Illustrate	
12mo	
MAIN and BROWN.—Questions on Subjects Connected with	th
the Marine Steam-Engine:	
	Βv
THOMAS J. MAIN, Professor of Mathematics, Royal Naval College	
and Thomas Brown, Chief Engineer, R. N. 12mo., cloth . \$1.	
MAIN and BROWN.—The Indicator and Dynamometer:	50
MAIN and BROWN.—The Indicator and Dynamometer:	
With their Practical Applications to the Steam-Engine. By Thom	AS
J. MAIN, M. A. F. R., Ass't S. Professor Royal Naval College	
Portsmouth, and Thomas Brown, Assoc. Inst. C. E., Chief Engine	er
R. N., attached to the R. N. College. Illustrated. 8vo \$1.	50
MAIN and BROWN.—The Marine Steam-Engine.	•
By THOMAS J. MAIN, F. R. Ass't S. Mathematical Professor at t	he
Royal Naval College, Portsmouth, and THOMAS BROWN, Asse	
Inst. C. E., Chief Engineer R. N. Attached to the Royal Na	
College. With numerous illustrations. 8vo	
MADMIN Commercial Tobles for the Headenic	1
MARTIN.—Screw-Cutting Tables, for the Use of Mechanic	;aı
Engineers:	
Showing the Proper Arrangement of Wheels for Cutting the Threa	
of Screws of any Required Pitch; with a Table for Making the U	ni-
versal Gas-Pipe Thread and Taps. By W. A. MARTIN, Engine	er.
8vo	50
MICHELL.—Mine Drainage:	-
Being a Complete and Practical Treatise on Direct-Acting Und	er.
ground Steam Pumping Machinery. With a Description of a lar	
number of the best known Engines, their General Utility and	80
Consider the best known Engines, then General Others and	.ne
Special Sphere of their Action, the Mode of their Application, a	na
their Merits compared with other Pumping Machinery. By STEPH	
MICHELL. Illustrated by 137 engravings. 8vo., 277 pages . \$6.	OU.
MOLESWORTH.—Pocket-Book of Useful Formulæ a	nd
Memoranda for Civil and Mechanical Engineers.	
By GUILFORD L. MOLESWORTH, Member of the Institution of Ci	vil
Engineers, Chief Resident Engineer of the Ceylon Railway. Fu	
bound in Pocket-book form \$1.	, CU

MOORE.—The Universal Assistant and the Complete Mechanic: Containing over one million Industrial Facts, Calculations, Receipts, Processes, Trades Secrets, Rules, Business Forms, Legal Items, Etc., in every occupation, from the Household to the Manufactory. By R. MOORE. Illustrated by 500 Engravings. 12mo. \$2.50 MORRIS,—Easy Rules for the Measurement of Earthworks: By means of the Prismoidal Formula. Illustrated with Numerous Wood-Cuts, Problems, and Examples, and concluded by an Extensive Table for finding the Solidity in cubic yards from Mean Areas. The whole being adapted for convenient use by Engineers, Surveyors, Contractors, and others needing Correct Measurements of Earthwork. By ELWOOD MORRIS, C. E. 8vo. MORTON.—The System of Calculating Diameter, Circumference, Area, and Squaring the Circle: Together with Interest and Miscellaneous Tables, and other information. By JAMES MORTON. Second Edition, enlarged, with the Metric System. 12mo. NAPIER.—Manual of Electro-Metallurgy: Including the Application of the Art to Manufacturing Processes. By JAMES NAPIER. Fourth American, from the Fourth London edition, revised and enlarged. Illustrated by engravings. 8vo. \$1.50 NAPIER.—A System of Chemistry Applied to Dyeing. By JAMES NAPIER, F. C. S. A New and Thoroughly Revised Edition. Completely brought up to the present state of the Science, including the Chemistry of Coal Tar Colors, by A. A. Fesquet, Chemist and Engineer. With an Appendix on Dyeing and Calico Printing, as shown at the Universal Exposition, Paris, 1867. Illustrated. 8vo. 422 pages \$5.00 NEVILLE.-Hydraulic Tables, Coefficients, and Formulæ, for finding the Discharge of Water from Orifices, Notches, Weirs, Pipes, and Rivers: Third Edition, with Additions, consisting of New Formulæ for the Discharge from Tidal and Flood Sluices and Siphons; general information on Rainfall, Catchment-Basins, Drainage, Sewerage, Water Supply for Towns and Mill Power. By JOHN NEVILLE, C. E. M. R. I. A.; Fellow of the Royal Geological Society of Ireland. Thick 12mo. \$3.5C NEWBERY.—Gleanings from Ornamental Art of every style: Drawn from Examples in the British, South Kensington, Indian, Crystal Palace, and other Museums, the Exhibitions of 1851 and 1862, and the best English and Foreign works. In a series of 100 exquisitely drawn Plates, containing many hundred examples. By ROBERT NEWBERY. 410. NICHOLLS. - The Theoretical and Practical Boiler-Maker and

Containing a variety of Useful Information for Employers of Labor, Foremen and Working Boiler-Makers, Iron, Copper, and Tinsmiths,

Engineer's Reference Book:

Draughtsmen, Engineers, the General Steam-using Public, and for the Use of Science Schools and Classes. By SAMUEL NICHOLLS. Illustrated by sixteen plates, 12mo.

NICHOLSON.—A Manual of the Art of Bookbinding:

Containing full instructions in the different Branches of Forwarding, Gilding, and Finishing. Also, the Art of Marbling Book-edges and Paper. By James B. Nicholson. Illustrated. 12mo., cloth \$2.25 NICOLLS .- The Railway Builder:

A Hand-Book for Estimating the Probable Cost of American Railway Construction and Equipment. By WILLIAM J. NICOLLS, Civil Engineer. Illustrated, full bound, pocket-book form \$2.00 NORMANDY.—The Commercial Handbook of Chemical An-

alysis:

Or Practical Instructions for the Determination of the Intrinsic or Commercial Value of Substances used in Manufactures, in Trades, and in the Arts. By A. NORMANDY. New Edition, Enlarged, and to a great extent rewritten. By HENRY M. NOAD, Ph.D., F.R.S., thick I 2mo. \$5.00

NORRIS.—A Handbook for Locomotive Engineers and Machinists:

Comprising the Proportions and Calculations for Constructing Locomotives; Manner of Setting Valves; Tables of Squares, Cubes, Areas, etc., etc. By SEPTIMUS NORRIS, M. E. New edition. Illustrated, 12mo.

NORTH.—The Practical Assayer:

Containing Easy Methods for the Assay of the Principal Metals and Alloys. Principally designed for explorers and those interested in By OLIVER NORTH. Illustrated. 12mo. Mines.

NYSTROM.—A New Treatise on Elements of Mechanics:

Establishing Strict Precision in the Meaning of Dynamical Terms: accompanied with an Appendix on Duodenal Arithmetic and Metrology. By JOHN W. NYSTROM, C. E. Illustrated. 8vo. \$2.00

NYSTROM.—On Technological Education and the Construction of Ships and Screw Propellers:

For Naval and Marine Engineers. By JOHN W. NYSTROM, late Acting Chief Engineer, U.S.N. Second edition, revised, with additional matter. Illustrated by seven engravings. 12mo.

O'NEILL.—A Dictionary of Dyeing and Calico Printing:
Containing a brief account of all the Substances and Processes in use in the Art of Dyeing and Printing Textile Fabrics; with Practical Receipts and Scientific Information. By Charles O'Neill, Analytical Chemist. To which is added an Essay on Coal Tar Colors and their application to Dyeing and Calico Printing. By A. A. FESQUET, Chemist and Engineer. With an appendix on Dyeing and Calico Printing, as shown at the Universal Exposition, Paris, 1867. 8vo., 491 pages

ORTON.-Underground Treasures:

How and Where to Find Them. A Key for the Ready Determination. of all the Useful Minerals within the United States. By JAMES

\$2.00

ORTON, A.M., Late Professor of Natural History in Vassar College, N. Y.; Cor. Mem. of the Academy of Natural Sciences, Philadelphia, and of the Lyceum of Natural History, New York; author of the "Andes and the Amazon," etc. A New Edition, with Additions. OSBORN.—The Metallurgy of Iron and Steel: Theoretical and Practical in all its Branches; with special reference to American Materials and Processes. By H. S. Osborn, LL. D., Professor of Mining and Metallurgy in Lafayette College, Easton, Pennsylvania. Illustrated by numerous large folding plates and wood-engravings. 8vo. OVERMAN.—The Manufacture of Steel: Containing the Practice and Principles of Working and Making Steel. A Handbook for Blacksmiths and Workers in Steel and Iron, Wagon Makers, Die Sinkers, Cutlers, and Manufacturers of Files and Hardware, of Steel and Iron, and for Men of Science and Art. By FREDERICK OVERMAN, Mining Engineer, Author of the "Manufacture of Iron," etc. A new, enlarged, and revised Edition. By A. A. FESQUET, Chemist and Engineer. 12mo. \$1
OVERMAN.—The Moulder's and Founder's Pocket Guide: A Treatise on Moulding and Founding in Green-sand, Dry-sand, Loam, and Cement; the Moulding of Machine Frames, Mill-gear, Hollowware, Ornaments, Trinkets, Bells, and Statues; Description of Moulds for Iron, Bronze, Brass, and other Metals; Plaster of Paris, Sulphur, Wax, etc.; the Construction of Melting Furnaces, the Melting and Founding of Metals; the Composition of Alloys and their Nature, etc., etc. By FREDERICK OVERMAN, M. E. A new Edition, to which is added a Supplement on Statuary and Ornamental Moulding, Ordnance, Malleable Iron Castings, etc. By A. A. FESQUET, Chemist and Engineer. Illustrated by 44 engravings. 12mo. PAINTER, GILDER, AND VARNISHER'S COMPANION: Containing Rules and Regulations in everything relating to the Aris of Painting, Gilding, Varnishing, Glass-Staining, Graining, Marbling, Sign-Writing, Gilding on Glass, and Coach Painting and Varnishing; Tests for the Detection of Adulterations in Oils, Colors, etc.; and a Statement of the Diseases to which Painters are peculiarly liable, with the Simplest and Best Remedies. Sixteenth Edition. Revised, with an Appendix. Containing Colors and Coloring-Theoretical and Practical. Comprising descriptions of a great variety of Additional Pigments, their Qualities and Uses, to which are added, Dryers, and Modes and Operations of Painting, etc. Together with Chevreul's Principles of Harmony and Contrast of Colors. 12mo. Cloth \$1.50 PALLETT.—The Miller's, Millwright's, and Engineer's Guide. By HENRY PALLETT. Illustrated. 12mo. \$3.00 PEARSE.—A Concise History of the Iron Manufacture of the American Colonies up to the Revolution, and of Pennsyl-

vania until the present time.

By JOHN B. PEARSE. Illustrated 12mo.

PERCY.—The Manufacture of Russian Sheet-Iron. By JOHN PERCY, M. D., F. R. S., Lecturer on Metallurgy at the Royal School of Mines, and to The Advance Class of Artillery Officers at the Royal Artillery Institution, Woolwich; Author of "Metallurgy." With Illustrations. 8vo., paper PERKINS.—Gas and Ventilation: Practical Treatise on Gas and Ventilation. With Special Relation to Illuminating, Heating, and Cooking by Gas. Including Scientific Helps to Engineer-students and others. With Illustrated Diagrams. By E. E. PERKINS. 12mo., cloth \$1.25 PERKINS AND STOWE.—A New Guide to the Sheet-iron and Boiler Plate Roller: Containing a Series of Tables showing the Weight of Slabs and Piles to Produce Boiler Plates, and of the Weight of Piles and the Sizes of Bars to produce Sheet-iron; the Thickness of the Bar Gauge in decimals; the Weight per foot, and the Thickness on the Bar or Wire Gauge of the fractional parts of an inch; the Weight per sheet, and the Thickness on the Wire Gauge of Sheet-iron of various dimensions to weigh 112 lbs. per bundle; and the conversion of Short Weight into Long Weight, and Long Weight into Short. Estimated and collected by G. H. PERKINS and J. G. STOWE. \$2.50 POWELL-CHANCE-HARRIS.-The Principles of Glass Making. By HARRY J. POWELL, B. A. Together with Treatises on Crown and Sheet Glass; by HENRY CHANCE, M. A. And Plate Glass, by H. G. HARRIS, Asso. M. Inst. C. E. Illustrated 18mo. \$1.50 PROTEAUX.—Practical Guide for the Manufacture of Paper and Boards. By A. PROTEAUX. From the French, by HORATIO PAINE, A. B., M. D. To which is added the Manufacture of Paper from Wood, by HENRY T. BROWN. Illustrated by six plates. 8vo. PROCTOR.—A Pocket-Book of Useful Tables and Formulæ for Marine Engineers. By FRANK PROCTOR. Second Edition, Revised and Enlarged. Full bound pocket-book form . \$1.50 REGNAULT.—Elements of Chemistry. By M. V. REGNAULT. Translated from the French by T. FORREST BETTON, M. D., and edited, with Notes, by JAMES C. BOOTH, Melter and Refiner U. S. Mint, and WILLIAM L. FABER. Metallurgist and Mining Engineer. Illustrated by nearly 700 wood engravings. Comprising nearly 1,500 pages. In two volumes, 8vo., cloth . RIFFAULT, VERGNAUD, and TOUSSAINT.-A Practical Treatise on the Manufacture of Colors for Painting: Comprising the Origin, Definition, and Classification of Colors; the Treatment of the Raw Materials; the best Formulæ and the Newest Processes for the Preparation of every description of Pigment, and the Necessary Apparatus and Directions for its Use; Dryers; the Testing, Application, and Qualities of Paints, etc., etc. By MM. RIFFAULT, VERGNAUD, and TOUSSAINT. Revised and Edited by M.

F. MALEPEYRE. Translated from the French, by A. A. FESQUET Chemist and Engineer. Illustrated by Eighty engravings. In one vol., 8vo., 659 pages
Steam-Engines: Including the Modelling, Constructing, and Management of Steam-Engines and Steam Boilers. With valuable illustrations. By STE-PHEN ROPER, Engineer. Sixteenth edition, revised and enlarged. 18mo., tucks, gilt edge \$2.00
ROPER.—Engineer's Handy-Book: Containing a full Explanation of the Steam-Engine Indicator, and its Use and Advantages to Engineers and Steam Users. With Formulæ for Estimating the Power of all Classes of Steam-Engines; also, Facts, Figures, Questions, and Tables for Engineers who wish to qualify themselves for the United States Navy, the Revenue Service, the Mercantile Marine, or to take charge of the Better Class of Sta- tionary Steam-Engines. Sixth edition. 16mo., 690 pages, tucks, gilt edge
ROPER.—Hand-Book of Land and Marine Engines: Including the Modelling, Construction, Running, and Management of Land and Marine Engines and Boilers. With illustrations. By STEPHEN ROPER, Engineer. Sixth edition. 12mo., tvcks, gilt edge. \$3.50
ROPER.—Hand-Book of the Locomotive: Including the Construction of Engines and Boilers, and the Construction, Management, and Running of Locomotives. By STEPHEN ROPER. Eleventh edition. 18mo., tucks, gilt edge \$2.50 ROPÉR.—Hand-Book of Modern Steam Fire-Engines. With illustrations. By STEPHEN ROPER, Engineer. Fourth edition, 12mo., tucks, gilt edge \$3.50 ROPER.—Questions and Answers for Engineers. This little book contains all the Questions that Engineers will be asked when undergoing an Examination for the purpose of procuring Licenses, and they are so plain that any Engineer or Fireman of ordinary intelligence may commit them to memory in a short time. By STEPHEN ROPER, Engineer. Third edition \$3.00 ROPER.—Use and Abuse of the Steam Boiler. By STEPHEN ROPER, Engineer. Eighth edition, with illustrations. 18mo., tucks, gilt edge \$2.00 ROSE.—The Complete Practical Machinist: Embracing Lathe Work, Vise Work, Drills and Drilling, Taps and Dies, Hardening and Tempering, the Making and Use of Tools, Tool Grinding, Marking out Work, etc. By Joshua Rose. Illustrated by 356 engravings. Thirteenth edition, thoroughly revised and in great part rewritten. In one vol., 12mo., 439 pages \$2.50 ROSE.—Mechanical Drawing Self-Taught:
Comprising Instructions in the Selection and Preparation of Drawing Instruments, Elementary Instruction in Practical Mechanical Draw-

ing, together with Examples in Simple Geometry and Elementary Mechanism, including Screw Threads, Gear Wheels, Mechanical Motions, Engines and Boilers. By JOSHUA ROSE, M. E., Author of "The Complete Practical Machinist," "The Pattern-maker's Assistant," "The Slide-valve." Illustrated by 330 engravings. 8vo., 313 pages ROSE.—The Slide-Valve Practically Explained: Embracing simple and complete Practical Demonstrations of the operation of each element in a Slide-valve Movement, and illustrating
the effects of Variations in their Proportions by examples carefully selected from the most recent and successful practice. By Joshua Rose, M. E., Author of "The Complete Practical Machinist," "The Pattern-maker's Assistant," etc. Illustrated by 35 engravings \$1.00
ROSS.—The Blowpipe in Chemistry, Mineralogy and Geology: Containing all Known Methods of Anhydrous Analysis, many Working Examples, and Instructions for Making Apparatus. By LIEUT. COLONEL W. A. Ross, R. A. F., G. S. With 120 Illustrations. 12mo
SHAW.—Civil Architecture: Being a Complete Theoretical and Practical System of Building, containing the Fundamental Principles of the Art. By EDWARD SHAW, Architect. To which is added a Treatise on Gothic Architecture, etc. By THOMAS W. SILLOWAY and GEORGE M. HARDING, Architects. The whole illustrated by 102 quarto plates finely engraved on copper.
SHUNK.—A Practical Treatise on Railway Curves and Location, for Young Engineers. By WILLIAM F. SHUNK, Civil Engineer. 12mo. Full bound pocket-book form
SLATER.—The Manual of Colors and Dye Wares. By J. W. SLATER. 12mo. \$3.75
SLOAN.—American Houses: A variety of Original Designs for Rural Buildings. Illustrated by twenty-six colored Engravings, with Descriptive References. By SAMUEL SLOAN, Architect, author of the "Model Architect," etc. etc. 8vo
SLOAN.—Homestead Architecture: Containing Forty Designs for Villas, Cottages, and Farm-houses, with Essays on Style, Construction, Landscape Gardening, Furniture, etc., etc. Illustrated by upwards of 200 engravings. By Samuel Sloan, Architect. 8vo. \$3.50
SMEATON.—Builder's Pocket-Companion: Containing the Elements of Building, Surveying, and Architecture; with Practical Rules and Instructions connected with the subject. By A. C. SMEATON, Civil Engineer, etc. 12mo \$1.50 SMITH.—A Manual of Political Economy.
By E. PESHINE SMITH. A new Edition, to which is added a full Index. 12mo

SMITH.—Parks and Pleasure-Grounds:
Or Practical Notes on Country Residences, Villas, Public Parks, and Gardens. By CHARLES H. J. SMITH, Landscape Gardener and
Gardens. By CHARLES H. J. SMITH, Landscape Gardener and
Garden Architect, etc., etc. 12mo \$2.00
SMITH.—The Dyer's Instructor:
Comprising Practical Instructions in the Art of Dyeing Silk, Cotton,
Wool, and Worsted, and Woolen Goods; containing nearly 800
Receipts. To which is added a Treatise on the Art of Padding; and
the Printing of Silk Warps, Skeins, and Handkerchiefs, and the
various Mordants and Colors for the different styles of such work.
By DAVID SMITH, Pattern Dyer. 12mo \$3.00
SMYTH.—A Rudimentary Treatise on Coal and Coal-Mining.
By Warrington W. Smyth, M. A., F. R. G., President R. G. S.
of Cornwall. Fifth edition, revised and corrected. With numer-
ous illustrations. 12mo
SNIVELY.—A Treatise on the Manufacture of Perfumes and
Kindred Toilet Articles.
By JOHN H. SNIVELY, Phr. D., Professor of Analytical Chemistry in
the Tennessee College of Pharmacy. 8vo \$3.00
SNIVELY.—Tables for Systematic Qualitative Chemical Anal-
ysis.
By John H. Snively, Phr. D. 8vo \$1.00
SNIVELY.—The Elements of Systematic Qualitative Chemical
Analysis:
A Hand-book for Beginners. By JOHN H. SNIVELY, Phr. D. 16mo.
\$2.00
STEWART.—The American System:
Speeches on the Tariff Question, and on Internal Improvements,
principally delivered in the House of Representatives of the United
States. By Andrew Stewart, late M. C. from Pennsylvania.
With a Portrait, and a Biographical Sketch. 8vo \$3.00
STOKES.—The Cabinet Maker and Upholsterer's Companion:
Comprising the Art of Drawing, as applicable to Cabinet Work;
Veneering, Inlaying, and Buhl-Work; the Art of Dyeing and Stain-
ing Wood, Ivory, Bone, Tortoise-Shell, etc. Directions for Lackers
ing, Japanning, and Varnishing; to make French Polish, Glues,
Cements, and Compositions: with numerous Receipts, useful to work.
men generally. By J. STOKES. Illustrated. A New Edition, with an Appendix upon French Polishing, Staining, Imitating, Varnishing,
an Appendix upon French Polishing, Staining, Imitating, Varnishing,
etc., etc. 12mo
STRENGTH AND OTHER PROPERTIES OF METALS:
Reports of Experiments on the Strength and other Properties of
Metals for Cannon. With a Description of the Machines for Testing
Metals, and of the Classification of Cannon in service. By Officers
of the Ordnance Department, U. S. Army. By authority of the Secre
tary of War. Illustrated by 25 large steel plates. Quarto . \$10.00
SULLIVAN.—Protection to Native Industry.
By Sir EDWARD SULLIVAN, Baronet, author of "Ten Chapters on

arrier a c . T 1 LO .
SYME.—Outlines of an Industrial Science.
By DAVID SYME. 12mo
TABLES SHOWING THE WEIGHT OF ROUND,
SQUARE, AND FLAT BAR IRON, STEEL, ETC.,
By Measurement. Cloth 63
TAYLOR.—Statistics of Coal:
Including Mineral Bituminous Substances employed in Arts and
Manufactures; with their Geographical, Geological, and Commercial
Distribution and Amount of Production and Consumption on the
American Continent. With Incidental Statistics of the Iron Manu-
facture. By R. C. TAYLOR. Second edition, revised by S. S. HALDE-
MAN. Illustrated by five Maps and many wood engravings. 8vo.,
cloth \$10.00
TEMPLETON.—The Practical Examinator on Steam and the
Steam-Engine:
With Instructive References relative thereto, arranged for the Use of
Engineers, Students, and others. By WILLIAM TEMPLETON, En-
gineer. 12mo. \$1.25 THAUSING.—The Theory and Practice of the Preparation of
Malt and the Fabrication of Beer:
With especial reference to the Vienna Process of Brewing. Elab-
orated from personal experience by Julius E. Thausing, Professor
at the School for Brewers, and at the Agricultural Institute, Mödling,
near Vienna. Translated from the German by WILLIAM T. BRANNT,
Thoroughly and elaborately edited, with much American matter, and
according to the latest and most Scientific Practice, by A. SCHWARZ
and Dr. A. H. BAUER. Illustrated by 140 Engravings. 8vo., 815
pages
THOMAS.—The Modern Practice of Photography:
By R. W. Thomas, F. C. S. 8vo.
THOMPSON.—Political Economy. With Especial Reference
to the Industrial History of Nations:
By ROBERT E. THOMPSON, M. A., Professor of Social Science in the
University of Pennsylvania. 12mo \$1.50
THOMSON.—Freight Charges Calculator:
By Andrew Thomson, Freight Agent. 24mo \$1.25
TURNER'S (THE) COMPANION:
Containing Instructions in Concentric, Elliptic, and Eccentric Turn-
ing; also various Plates of Chucks, Tools, and Instruments; and
Directions for using the Eccentric Cutter, Drill, Vertical Cutter, and
Circular Rest; with Patterns and Instructions for working them.
12mo
TURNING: Specimens of Fancy Turning Executed on the
Hand or Foot-Lathe:
With Geometric, Oval, and Eccentric Chucks, and Elliptical Cutting
Frame. By an Amateur. Illustrated by 30 exquisite Photographs.
4to
JRBIN-BRULLA Practical Guide for Puddling Iron and
Steel.
By ED. URBIN, Engineer of Arts and Manufactures. A Prize Essay.

read before the Association of Engineers, Graduate of the School of Mines, of Liege, Belgium, at the Meeting of 1865-6. To which is added A Comparison of the Resisting Properties of Iron and Steel. By A. Brull. Translated from the French by A. A. Fesquet, Chemist and Engineer. 8vo. \$1.00

VAILE.—Galvanized-Iron Cornice-Worker's Manual:

VILLE.—On Artificial Manures:

VILLE.—The School of Chemical Manures:

VOGDES.—The Architect's and Builder's Pocket-Companion and Price-Book:

Consisting of a Short but Comprehensive Epitome of Decimals, Duodecimals, Geometry and Mensuration; with Tables of United States Measures, Sizes, Weights, Strengths, etc., of Iron, Wood, Stone, Brick, Cement and Concretes, Quantities of Materials in given Sizes and Dimensions of Wood, Brick and Stone; and full and complete Bills of Prices for Carpenter's Work and Painting; also, Rules for Computing and Valuing Brick and Brick Work, Stone Work, Painting, Plastering, with a Vocabulary of Technical Terms, etc. By Frank W. Vogdes, Architect, Indianapolis, Ind. Enlarged, revised, and corrected. In one volume, 368 pages, full-bound, pocket-book form, gilt edges

1.50

WAHL.—Galvanoplastic Manipulations:

A Practical Guide for the Gold and Silver Electroplater and the Galvanoplastic Operator. Comprising the Electro-Deposition of all Metals by means of the Battery and the Dynamo-Electric Machine, as well as the most approved Processes of Deposition by Simple Immersion, with Descriptions of Apparatus, Chemical Products employed in the Art, etc. Based largely on the "Manipulations Hydroplastiques" of Alfred Roseleur. By William H. Wahl, Ph. D. (Heid), Secretary of the Franklin Institute. Illustrated by 189 engravings. 8vo., 656 pages \$7.50

WALTON.—Coal-Mining Described and Illustrated:

By Thomas H. Walton, Mining Engineer. Illustrated by 24 large and elaborate Plates, after Actual Workings and Apparatus. \$5.00

WARE.—The Sugar Beet.

Including a History of the Beet Sugar Industry in Europe, Varieties of the Sugar Beet, Examination, Soils, Tillage, Seeds and Sowing, Yield and Cost of Cultivation, Harvesting, Transportation, Conservation, Feeding Qualities of the Beet and of the Pulp, etc. By LEWIS S. WARE, C. E., M. E. Illustrated by ninety engravings. 8vo.

WARN.—The Sheet-Metal Worker's Instructor:

For Zinc, Sheet-Iron, Copper, and Tin-Plate Workers, etc. Containing a selection of Geometrical Problems; also, Practical and Simple Rules for Describing the various Patterns required in the different branches of the above Trades. By REUBEN H. WARN, Practical Tin-Plate Worker. To which is added an Appendix, containing Instructions for Boiler-Making, Mensuration of Surfaces and Solids, Rules for Calculating the Weights of different Figures of Iron and Steel, Tables of the Weights of Iron, Steel, etc. Illustrated by thirty-two Plates and thirty-seven Wood Engravings. 8vo. \$3.00

WARNER.—New Theorems, Tables, and Diagrams, for the Computation of Earth-work:

WATSON,-A Manual of the Hand-Lathe:

Comprising Concise Directions for Working Metals of all kinds, Ivory, Bone and Precious Woods; Dyeing, Coloring, and French Polishing; Inlaying by Veneers, and various methods practised to produce Elaborate work with Dispatch, and at Small Expense. By EGBERT P. WATSON, Author of "The Modern Practice of American Machinists and Engineers." Illustrated by 78 engravings. \$1.50

WATSON.—The Modern Practice of American Machinists and Engineers:

Including the Construction, Application, and Use of Drills, Lathe Tools, Cutters for Boring Cylinders, and Hollow-work generally, with the most Economical Speed for the same; the Results verified by Actual Practice at the Lathe, the Vise, and on the Floor. Together

with Workshop Management, Economy of Manufacture, the Steam-Engine, Boilers, Gears, Belting, etc., etc. By EGBERT P. WATSON. Illustrated by eighty-six engravings. 12mo. WATSON.—The Theory and Practice of the Art of Weaving by Hand and Power: With Calculations and Tables for the Use of those connected with the Trade. By JOHN WATSON, Manufacturer and Practical Machine-Maker. Illustrated by large Drawings of the best Power Looms. 8vo. WATT .- The Art of Soap Making: A Practical Hand-book of the Manufacture of Hard and Soft Soaps, Toilet Soaps, etc., including many New Processes, and a Chapter on the Recovery of Glycerine from Waste Leys. By ALEXANDER WATT. Ill. 12mo. \$3.00 WEATHERLY.-Treatise on the Art of Boiling Sugar, Crystailizing, Lozenge-making, Comfits, Gum Goods, And other processes for Confectionery, etc., in which are explained, in an easy and familiar manner, the various Methods of Manufacturing every Description of Raw and Refined Sugar Goods, as sold by Confectioners and others. 12mo. WEDDING.—Elements of the Metallurgy of Iron. By Dr. HERMANN WEDDING, Royal Privy Counsellor of Mines, Berlin, Prussia. Translated from the second revised and rewritten German edition. By WILLIAM T. BRANNT, Graduate of the Royal Agricultural College at Eldena, Prussia. Edited by WILLIAM H. WAHL, Ph. D., Secretary of the Franklin Institute, Philadelphia. Illustrated by about 250 engravings. 8vo., about 500 pages (In prep. WEINHOLD .- Introduction to Experimental Physics, Theoretical and Practical. Including directions for Constructing Physical Apparatus and for Making Experiments. By ADOLF F. WEINHOLD, Professor in the Royal Technical School at Chemnitz. Translated and edited, with the author's sanction, by BENJAMIN LOEWY, F. R. A. S., with a preface, by G. C. FOSTER, F. R. S. Illustrated by three colored plates and 404 wood-cuts. 8vo., 848 pages WIGHTWICK.—Hints to Young Architects: Comprising Advice to those who, while yet at school, are destined to the Profession; to such as, having passed their pupilage, are about to travel; and to those who, having completed their education, are about to practise. Together with a Model Specification involving a great variety of instructive and suggestive matter. By George Wightwick, Architect. A new edition, revised and considerably enlarged; comprising Treatises on the Principles of Construction and Design. By G. HUSKISSON GUILLAUME, Architect. Numerous Illustrations. One vol. 12mo. . \$2.00


WILL.—Tables of Qualitative Chemical Analysis.


With an Introductory Chapter on the Course of Analysis. By Professor Heinrich Will, of Giessen, Germany. Third American,


from the eleventh German edition. Edited by CHARLES F. HIMES Ph. D., Professor of Natural Science, Dickinson College, Carlisle, Pa 8vo.
WILLIAMS.—On Heat and Steam: Embracing New Views of Vaporization, Condensation, and Explosion. By CHARLES WYE WILLIAMS, A. I. C. E. Illustrated 8vo. \$350
WILSON.—A Treatise on Steam Boilers: Their Strength, Construction, and Economical Working. By ROBERT WILSON. Illustrated 12mo. \$2.50 WILSON.—Cotton Carder's Companion: In which is given a description of the manner of Picking, Baling Marketing, Opening, and Carding Cotton; to which is added a list of valuable Tables, Rules, and Receipts, by FOSTER WILSON. 12mo.
WILSON.—First Principles of Political Economy: With Reference to Statesmanship and the Progress of Civilization By Professor W. D. WILSON, of the Cornell University. A new and revised edition. 12mo
By F. Wöhler, Professor of Chemistry in the University of Göttin gen. Edited by Henry B. Nason, Professor of Chemistry in the Renssalaer Polytechnic Institute, Troy, New York. Illustrated 12mo. \$3.00 WORSSAM.—On Mechanical Saws: From the Transactions of the Society of Engineers, 1869. By S. W WORSSAM, JR. Illustrated by eighteen large plates. 8vo. \$2.50

RECENT ADDITIONS.
ANDERSON—The Prospector's Hand-Book: A Guide for the Prospector and Traveler in Search of Metal Bearing or other Valuable Minerals. By J. W. Anderson. 52 Illustrations 12mo. \$1.50 BILGRAM.—Slide-Valve Gears:
A new, graphical method for Analyzing the Action of Slide-Valves moved by Eccentrics, Link Motions, and Cut-off Gears, offering easy means for properly designing Valves and Valve-Gears, and for establishing the comparative merits of their various constructions. By HUGO BILGRAM, M. E. Illustrated. 16mo
CREW.—A Practical Treatise on Petroleum:
Comprising its Geographical Distribution, its Geology, Chemistry, Mining, Refining, Preparation, and Uses. Together with a Description of Gas Wells and the Application of Gas as Fuel, etc. By BENJAMIN J. CREW. Illustrated. 8vo. (In preparation.) CROOKES.—Select Methods in Chemical Analysis (Chiefly
Inorganic):
By WILLIAM CROOKES, F. R. S., V. P. C. S. 2d edition, re-written and greatly enlarged. Illustrated by 37 wood-cuts. 725 pp. 8vo. \$9.50

DAVIS .- A Treatise on Steam-Boiler Incrustation and Methods for Preventing Corrosion and the Formation of Scale: By CHARLES T. DAVIS. Illustrated by 65 engravings. 8vo. \$2.00 DAVIS.—The Manufacture of Paper: Being a Description of the various Processes for the Fabrication, Coloring and Finishing of every kind of Paper, Including the Different Raw Materials and the Methods for Determining their Values, the Tools, Machines and Practical Details connected with an intelligent and a profitable prosecution of the art, with special reference to the best American Practice. To which are added a History of Paper, complete Lists of Paper-Making Materials, List of American Machines, Tools and Processes used in treating the Raw Materials, and in Making, Coloring and Finishing Paper. By CHARLES T. DAVIS. Illustrated by 156 engravings. 500 pages, 8vo. Hand-Book of Useful Tables for the Lumberman, Farmer and Mechanic: Containing Accurate Tables of Logs Reduced to Inch Board Measure, Plank, Scantling and Timber Measure; Wages and Rent, by Week or Month; Capacity of Granaries, Bins and Cisterns; Land Measure, Interest Tables, with Directions for Finding the Interest on any sum at 4, 5, 6, 7 and 8 per cent., and many other Useful Tables. 32 mo., boards. 186 pages MAKINS.—A Manual of Metallurgy: By George Hogarth Makins, M. R. C. S. S. C. S. Illustrated by 100 engravings. Second edition rewritten and much enlarged. 8vo., 592 pages \$3.00 ROPER.—Instructions and Suggestions for Engineers and Firemen: By Stephen Roper, Engineer \$2.00 ROPER.—The Steam Boiler: Its Care and Management: By STEPHEN ROPER, Engineer. 12mo., tuck, gilt edges . \$2.00 ROPER.—The Young Engineer's Own Book: Containing an Explanation of the Principle and Theories on which the Steam Engine as a Prime Mover is Based. By STEPHEN ROPER, Engineer. 160 illustrations, 363 pages. 18mo., tuck ROSE.-Modern Steam-Engines: An Elementary Treatise upon the Steam-Engine, written in Plain language; for Use in the Workshop as well as in the Drawing Office. Giving Full Explanations of the Construction of Modern Steam-Engines: Including Diagrams showing their Actual operation. Together with Complete but Simple Explanations of the operations of Various Kinds of Valves, Valve Motions, and Link Motions, etc., thereby Enabling the Ordinary Engineer to Clearly Understand the Principles Involved in their Construction and Use, and to Plot out their Movements upon the Drawing Board. By JOSHUA ROSE, M. E., Author of "The Complete Practical Machinist," "The Pattern Maker's Assistant," "The Slide Valve" and "Mechanical Drawing Self-Taught." Illustrated by over 400 engravings. In one volume, 4to, 320 pages .







11-

•

.

•

.

.

·

.

•

.

•

.

.

•





89089674972



b89089674972a